	To Appropriate District	State of	New Me	xico		Form C-103	
Office District I	Energy, Minerals and Natural Resources				June 19, 2008		
1625 N. French District II	15 N. French Dr., Hobbs, NM 88240 trict II				WELL API NO. <b>30-007-20379</b>		
1301 W. Grand A District III	W. Grand Ave., Artesia, NM 88210  OIL CONSERVATION DIVISION  1220 South St. Francis Dr.				5. Indicate Typ		
	00 Rio Brazos Rd., Aztec, NM 87410				STATE 6. State Oil & 0	☐ FEE ☒ Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM						Sus Louse 110.	
87505 ILULIVLU QUU SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name							
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLLIG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUGHY - 4  2: 07							
1. Type of Well: Oil Well Gas Well Other COAL BED METHANE					8. Well Number 91		
2. Name of Operator  EL PASO E & P COMPANY, L.P.					9. OGRID Number 180514		
3. Address of Operator					10. Pool name		
PO BOX 190 RATON, NM 87740							
4. Well Location							
	Letter <u>M</u> :	1135 feet from the			<del></del>	the <u>WEST</u> line	
Section	on <b>27</b>	Township 31N  11. Elevation (Show wheel)	Range		IPM Count	ty COLFAX	
8377'							
12 Cheels Assuranciate Day to Indicate Nature of Nation Day on Other Date							
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☒							
PULL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMENT JOB							
DOWNHOLE COMMINGLE							
OTHER:			П	OTHER:		П	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date							
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion							
or recompletion.							
10/21/2009	MIRU LD rods an						
10/22/2009							
	Test to 500 psi. Failed. TOOH to 748'. Test to 500 psi. Failed. TOOH to 425'. Test to 500 psi. Test good.						
10/23/2009 TOOH, NU BOP. Release BP at 425'. Reset @ 490'. Good. Reset @ 554', Good.							
		d. Reset @ 587', Good.		598', Good. Reset (	<u>a</u> 619. Isolate Le	ak.	
10/28/2009	Made 6 swab runs. TIH w/ 5 ½" CIBP. Set at 1071'.  MOB Mack's Cement Equipment and spot in. TIH to 1071'. Tag CIBP, pull up 16". RU cement pump.						
10/20/2000	Mix 10 sks. TOOH to 620'. LD 14 jts. Mix 20 sks. TOOH.						
10/29/2009	0/29/2009 RU WH with 5 ½" to 2" swedge. MIT test to 500 psi, Good. Tag cement plug @ 467', pump 20 sks  Cement. Brought cement up to 300'. TOOH LD 2 7/8" tubing. Pump 10 sks cement to surface. RDMO.						
10/30/2009		and set marker as per N					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE_	Thurley X. F	nitchall_TIT	LE <u>Sr. F</u>	Regulatory Analyst	Da	ATE 11/02/2009	
	ı						
Type or print name Shirley A. Mitchell E-mail address: shirley.mitchell@elpaso.com PHONE: (575) 445-6785  For State Use Only							
APPROVED BY:							
- OHAIMOHD OF A							