Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-045-21789
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Florance R
1. Type of Well:	8. Well Number
Oil Well Gas Well X Other	8A
2. Name of Operator	9. OGRID Number
BP America Production Company	000778
3. Address of Operator	10. Pool name or Wildcat
P O Box 3092 Houston, TX 77253 Attn: Mary Corley Rm 19.171 4. Well Location	Blanco MV & Basin FC
Section 14 Township 30N Range 09W 11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
6042'GL	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attache	
Pit Location: ULSectTwpRngPit typeDepth to GroundwaterDistance	
Distance from nearest surface water Below-grade Tank Location ULSectTwp_	Rng ;
feet from theline andfeet from theline	
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK [] PLUG AND ABANDON [] REMEDIAL WOR	SEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF: K ALTERING CASING LLING OPNS. PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	SEQUENT REPORT OF: K ALTERING CASING LLING OPNS. PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE CASING TEST AND COMMENCE DRI	SEQUENT REPORT OF: K ALTERING CASING LLING OPNS. PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB	SEQUENT REPORT OF: K ALTERING CASING ALTERING OPNS. PLUG AND ABANDONMENT ND ABANDONMENT d give pertinent dates, including estimated date tach wellbore diagram of proposed completion on the Blanco Mesaverde and Basin
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB OTHER: Surface Commingling X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. OTHER: surface commingle production	SEQUENT REPORT OF: K ALTERING CASING ALTERING OPNS. ALTERING CASING ABANDONMENT ABANDONMENT ND ABANDONMENT d give pertinent dates, including estimated date tach wellbore diagram of proposed completion on the Blanco Mesaverde and Basin
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB OTHER: Surface Commingling X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. OTHER: surface commingle production	SEQUENT REPORT OF: K ALTERING CASING ALTERING OPNS. PLUG AND ABANDONMENT ND ABANDONMENT d give pertinent dates, including estimated date tach wellbore diagram of proposed completion on the Blanco Mesaverde and Basin
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB OTHER: Surface Commingling X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. OTHER: surface commingle production	SEQUENT REPORT OF: K ALTERING CASING ALTERING OPNS. PLUG AND ABANDONMENT ND ABANDONMENT d give pertinent dates, including estimated date tach wellbore diagram of proposed completion on the Blanco Mesaverde and Basin
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB OTHER: Surface Commingling X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. OTHER: surface commingle production	SEQUENT REPORT OF: K ALTERING CASING ALTERING OPNS. PLUG AND ABANDONMENT ND ABANDONMENT d give pertinent dates, including estimated date tach wellbore diagram of proposed completion on the Blanco Mesaverde and Basin
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB OTHER: Surface Commingling X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. OTHER: surface commingle production	SEQUENT REPORT OF: K ALTERING CASING ALTERING OPNS. PLUG AND ABANDONMENT ND ABANDONMENT d give pertinent dates, including estimated date tach wellbore diagram of proposed completion on the Blanco Mesaverde and Basin
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB OTHER: Surface Commingling X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. OTHER: surface commingle production	SEQUENT REPORT OF: K ALTERING CASING ILLING OPNS. PLUG AND ABANDONMENT ND ABANDONMENT Id give pertinent dates, including estimated date tach wellbore diagram of proposed completion On the Blanco Mesaverde and Basin . e and belief. I further certify that any pit or below-
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE CASING TEST AN COMPLETION COMPLETION OTHER: OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 3P America Production Company request permission to surface commingle production Fruitland Coal Pools from the subject well . Please see attached for additional details Mathematical Production above is true and complete to the best of my knowledge	SEQUENT REPORT OF: K ALTERING CASING ILLING OPNS. PLUG AND ABANDONMENT ND ABANDONMENT Id give pertinent dates, including estimated date tach wellbore diagram of proposed completion on the Blanco Mesaverde and Basin description description and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE CASING TEST AN PULL OR ALTER CASING MULTIPLE CASING TEST AN OTHER: Surface Commingling X OTHER: OTHER: Surface Commingling X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 3P America Production Company request permission to surface commingle production Graditional details Fruitland Coal Pools from the subject well . Please see attached for additional details hereby certify that the information above is true and complete to the best of my knowledge general permit SIGNATURE May Multiple Sr. Regulatory .	SEQUENT REPORT OF: K ALTERING CASING ILLING OPNS. PLUG AND ABANDONMENT ND ABANDONMENT Id give pertinent dates, including estimated date tach wellbore diagram of proposed completion on the Blanco Mesaverde and Basin description description and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE CASING TEST AN COMPLETION CHANGE PLANS CASING TEST AN OTHER: Surface Commingling X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. OTHER: 3P America Production Company request permission to surface commingle production Fruitland Coal Pools from the subject well . Please see attached for additional details Preby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed/according to NMOCD guidelines], a general permit [] SIGNATURE May May TITLE Sr. Regulatory	SEQUENT REPORT OF: K ALTERING CASING ILLING OPNS. PLUG AND ABANDONMENT ND Image: Completion of the second
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. OTHER: 3P America Production Company request permission to surface commingle production Fruitland Coal Pools from the subject well. Please see attached for additional details Production Company request permission to surface commingle production Fruitland Coal Pools from the subject well. Please see attached for additional details SIGNATURE Mary Corley TITLE Sr. Regulatory SIGNATURE Mary Corley E-mail address: corleyml@bp.com	SEQUENT REPORT OF: K ALTERING CASING ILLING OPNS. PLUG AND ABANDONMENT ND Image: Completion of the second
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB OTHER: Surface Commingling Image: Completed operations. OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 3P America Production Company request permission to surface commingle production. Brancica Production Company request permission to surface commingle production. Breeby certify that the information above is true and complete to the best of my knowledge trade tank has been/will be constructed or closed/according to NMOCD guidelines , a general permit SIGNATURE Image: Complete test open print name Mary Orley E-mail address: corleyml@bp.com This Space for State Use) Image: Complete With test open print name Image: Complete With test open print name	SEQUENT REPORT OF: K ALTERING CASING ALTERING CASING ALTERING OPNS. PLUG AND ABANDONMENT ND ABANDONMENT ND ABANDONMENT Ad give pertinent dates, including estimated date tach wellbore diagram of proposed completion on the Blanco Mesaverde and Basin the Blanco Mesaverde and Basin the Blanco Mesaverde and Basin Analyst DATE 09/29/2004 Telephone No. 281-366-4491