

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-31690

Release Notification and Corrective Action

NMLB1125248273

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P.	260737	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 432-556-8730
Facility Name Poker Lake Unit Well #205 at Battery PLU-158		Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No
-----------------------	-----------------------	----------

LOCATION OF RELEASE

Unit Letter A	Section 7	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.237400 Longitude W 103.914150

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 30 bbls of crude oil.	Volume Recovered: 25 bbls
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence 8/22/11, Hour unknown	Date and Hour of Discovery 8/22/11 8:54 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tim NMOCD	
By Whom? Tony Savoie	Date and Hour 8/22/11 1:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\* A flow line from the PLU-205 pumping well developed a leak at the PLU-158 Battery, a repair clamp was installed on the line.

Describe Area Affected and Cleanup Action Taken.\* Approximately 300 sq. ft. of pasture land on the north side of the battery pad, all of the free oil was picked up with a vacuum truck. A remediation plan will be developed in accordance with the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by: <u>[Signature]</u>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: SEP 13 2011	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/11/11 Phone: 432-556-8730	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 10/13/2011	

\* Attach Additional Sheets If Necessary



2RA-900