

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

JAN 30 2012

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact John W. Gates
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name EVGSAU 3467-018	Facility Type Oil and Gas

Surface Owner State Of New Mexico	Mineral Owner State Of New Mexico	Lease No 300250299900
--	--	------------------------------

LOCATION OF RELEASE

Unit Letter B	Section 34	Township 17S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude **32degrees 47' 48.4"**

Longitude **103degrees 26' 35.1"**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 572.1bbl (0oil, 572.1 bblswater)	Volume Recovered (0oil, 240 bblswater)
Source of Release Failed threaded section on a 2 7/8" X 2" fiberglass changeover into a 2" fiberglass flange	Date and Hour of Occurrence 1/26/12 1717	Date and Hour of Discovery 1/27/12 0620
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking NMOCD	
By Whom? John Gates	Date and Hour 1/27/12 0900	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

It was determined that the release originated from a 2 7/8" to 2" fiberglass changeover in the threaded area on the 2" end where the changeover was screwed into a 2" fiberglass flange.

Describe Area Affected and Cleanup Action Taken.*

The affected area is a 423' X 423' X 2" area of well pad and pasture land. Vacuum trucks were called and ~240 bbls of produced water was recovered

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John W. Gates	Approved by ENV SPECIALIST:  District Supervisor	
Title: HSER Lead	Approval Date: 1/30/12	Expiration Date: 3/30/12
E-mail Address: John.W.Gates@conocophillips.com	Conditions of Approval: DELIVERATE RELEASE HORIZONTALLY AND VERTICALLY, SUBMIT FINAL C-141 BY 3/30/12.	Attached <input type="checkbox"/> IRP-1-12-2780
Date: 01/30/12 Phone: 505.391.3158		

• Attach Additional Sheets If Necessary

FEB 06 2012