

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

nMLB1209747032

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. 16696	Contact	Chancey Summers
Address	1017 W. Stanolind Road; Hobbs, NM 88240	Telephone No.	575-397-8216
Facility Name	RiverBend B-11 Battery	Facility Type	Gathering

Surface Owner	BLM	Mineral Owner		Lease No:	NM 81586
---------------	-----	---------------	--	-----------	----------

#### LOCATION OF RELEASE

River Bend Fed #7 30-015-27994

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	23	24S	29E					Eddy County, NM

Latitude 32.20367°

Longitude 103.96233°

#### NATURE OF RELEASE

Type of Release	Oil	Volume of Release	151 bbls	Volume Recovered	73 bbls
Source of Release	Victaulic clamp failure at circulating pump	Date and Hour of Occurrence	01/01/2012 @ 10:00 a.m.	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD, Jim Amos-BLM		
By Whom?.	Chancey Summers	Date and Hour	01/11/2012 @ 10:12 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

**RECEIVED**  
MAR 26 2012  
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A Victaulic clamp failure at the circulating pump caused 151 bbls of oil to leak onto the ground. 73 bbls of oil were recovered via vacuum truck. Remediation efforts continue and will be performed according to OCD and BLM guidelines.

Describe Area Affected and Cleanup Action Taken.\*

Remediate to NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Chancey Summers	Approved by District Supervisor <u>Mike Bratcher</u>		
Title: HES Specialist	Approval Date: APR 06 2012	Expiration Date:	
E-mail Address: chancey_summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 3-22-12 Phone: (575) 397-8216	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 5/6/2012		

\* Attach Additional Sheets If Necessary


2RP-1083



PHONE (575) 397-6388 • FAX (575) 397-0397 • 1324 W MARLAND • P.O BOX 805 • HOBBS NM 88241-0805  
E-MAIL: cbrunson@bbcinternational.com

---

March 22, 2012



Mr. Mike Bratcher  
New Mexico Oil Conservation Division  
811 S. First Street  
Artesia, NM 88210

Re: Oxy Initial C-141 Notifications for AMAX 24 #8 CTB, Cypress 34 Federal 4H, and  
Riverbend B-11 Battery

Dear Mr. Bratcher:

On behalf of Oxy USA, BBC International, Inc. is pleased to enclose the initial C-141 notifications for the above referenced sites for your records.

Please let us know if you require any additional information.

Sincerely,

Cliff P. Brunson  
President

Enclosures

**Bratcher, Mike, EMNRD**

---

**From:** Chancey\_Summers@oxy.com  
**Sent:** Wednesday, January 11, 2012 10:12 AM  
**To:** Dusty\_Wilson@oxy.com; Bratcher, Mike, EMNRD; jamos@blm.gov  
**Cc:** cbrunson@bbcinternational.com; kswinney@bbcinternational.com  
**Subject:** Riverbend Federal B-11

All, this email is to inform you of a Reportable leak that Oxy Permian had at the Riverbend Federal B-11. Total release was 151 bbls of oil, with 73 recovered. The leak was due to failure of a Victaulic clamp at the circulating pump. Battery is located in Section 23, Township 24s, and Range 29E of Eddy County. Oxy will be performing some initial clean up of the surface soils and gathering soil samples to be tested for impact in the near future. A C-141 will follow. If you have any questions feel free to reply.

Thank You  
C.J. Summers  
HES Specialist  
Cell # 575-631-9436  
Office # 575-397-8216  
[Chancey\\_Summers@oxy.com](mailto:Chancey_Summers@oxy.com)  
"When the blind lead the blind, get out of the way!"

"You will never succeed, if not given the chance to fail."