	Dr., Hodds, r	NM 882490 1 L		VED Energy Min	nerals	New Mex and Natura	100 l Resources			Re	Form C-14 vised October 10, 200
Sibtriet III			UN 20	$\frac{2012}{\text{oll C}}$	Conse	servation Division uth St. Francis Dr. 1 Fe, NM 87505			Submit 2 Copies to appropriat District Office in accordanc with Rule 116 on bac		
220 S St. Fran	icis Dr , Santa	Fe, 18750	CD AI	RTESIA Z20 Sa	inta F	e, NM 875	505			W	side of for
······	· · ·	<u> </u>		ease Notific				ctior	1		
nmursia	170 38	22	1.01			OPERA				al Report	Final Rep
Name of Co	ompa'ny BC	DPCO, L.P.		26073		Contact Tor					· · · · · · · · · · · · · · · · · · ·
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Facility Name Poker Lake Unit #78 SWD Tank Battery						Telephone No. 432-556-8730					
Facility Na	me Poker L	.ake Unit #7	8 SWD	Tank Battery		Facility Typ	e E&P				
Surface Owner Federal Mineral Own						r Federal			Lease No.		
				LOCA	OITA	N OF REI	LEASE		30-0	15-2	17536
Unit Letter A	Section 25	Township 24S	Range 30E	Feet from the		/South Line	Feet from the	East/	West Line	County Eddy	· /
			1.	Latitude_N 32.1	94069	Longitu	ide W 103.827	614			
				NAT	URE	OF REL	EASE				
Type of Rele	ase: Crude	oil and produ	ced water			Volume of	Release: 4000				820 bbls. From the
Source of Release: SWD Tank Battery Was Immediate Notice Given? Yes No Not Required						produced v crude oil.	water and 20 bbls	sof	damaged containment. None from the surface area outside the containment.		
						Date and H	lour of Occurren	ce	Date and	Hour of Dis	
						5/26/12 9:0 If YES, To			8/20/11 8	8:00 a.m.	·, · · ·
							o wnom? emergency #104,	Jim Am	os BLM		
By Whom? Tony Savoie										and 9:24 p.m	. to the NMOCD
Was a Watercourse Reached?							olume Impacting			P.m	
		L] Yes [>	() No							
If a Waterco	urse was Im	pacted, Descr	ibe Fully.	*							
Describe Cau adjacent tank	use of Proble	em and Reme containment	dial Actic	n Taken.* Lightin	ig struc	k the facility g	gun barrel tanks o	ausing i	mmediate c	lamage to be	th tanks and the
adjacent tank	ts inside the	containment.	All of the	n Taken.* Lightin production was i the fire put out by	mmedia	ately shut dow	n and incoming	streams	were divert	ed to other fa	acilities. Fire crew
adjacent tank from Malaga	ts inside the and Loving	containment. g responded to	All of the and had	e production was is the fire put out by	mmedia 11:00 j	ately shut dow o.m. Vacuum	n and incoming trucks.started rer	streams noving v	were divert vater from 1	ed to other father damaged	acilities. Fire crew containment.
adjacent tank from Malaga Describe Are fiberglass gu	and Loving a Affected and barrel tank	containment. gresponded to and Cleanup A ks were nearly	All of the and had Action Ta	e production was is the fire put out by ken.*The salt wate ely destroyed due	mmedia 11:00 j er dispo to the l	ately shut dow o.m. Vacuum sal tanks were ghtning hit an	n and incoming trucks.started rer c located inside a d fire. The 500 b	streams noving v poly lin bbl steel	were divert vater from t ed metal co oil skim tar	ed to other fathe damaged	acilities. Fire crew containment. Two of the 1000 b everely damaged
adjacent tank from Malaga Describe Are fiberglass gu along with or	and Loving and Loving a Affected a n barrel tank ne of the 10	containment. g responded to and Cleanup ks were nearly 00 bbl fibergl	All of the o and had Action Ta y complet ass water	e production was is the fire put out by ken.*The salt wate ely destroyed due storage tanks. The	mmedia 11:00 p er dispo to the l ere were	ately shut dow o.m. Vacuum sal tanks were ghtning hit an a total of 4-1	n and incoming trucks.started rer e located inside a id fire. The 500 b 000 bbl fiberglas	streams noving v poly lin obl steel	were divert vater from t ed metal co oil skim tar e tanks, (2)	ed to other fathe damaged ontainment. 7 hk was also s 1000 bbl gu	acilities. Fire crew containment. Two of the 1000 b everely damaged n barrels, and (1)
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being r	and Loving and Loving a Affected a n barrel tank ne of the 100 skim tank in released by t	containment. g responded to and Cleanup A ks were nearl 00 bbl fibergi uside the conta the damaged	All of the o and had Action Ta y complet ass water ainment a tanks. The	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh	mmedia 11:00 p er dispo to the l ere were ent was here the	ately shut dow o.m. Vacuum sal tanks were ghtning hit ar a total of 4-1 damaged by c containment	n and incoming trucks started rer e located inside a d fire. The 500 b 000 bbl fiberglas falling piping and was breached all	streams noving v poly lin bbl steel ss storag d fire; ho owing c	were divert vater from t ed metal co oil skim tar e tanks, (2) owever it w rude oil and	ed to other fi the damaged ontainment. 7 hk was also s 1000 bbl gu as holding m d produced v	acilities. Fire crew containment. Two of the 1000 b everely damaged n barrels, and (1) ost some of the vater to travel off-
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being r site into the p	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to pasture. The	containment. g responded to and Cleanup A ks were nearl 00 bbl fibergi uside the conta the damaged a affected area	All of the o and had Action Ta y complet ass water ainment a tanks. The	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas whether sture measured app	mmedia 11:00 p er dispo to the l ere were ent was here the proxima	ately shut dow o.m. Vacuum sal tanks were ghtning hit an e a total of 4-1 damaged by c containment ately 21,680 se	n and incoming trucks started rer e located inside a d fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling	streams noving v poly lin bbl steel s storag d fire; ho owing c event w	were divert vater from t ed metal co oil skim tar e tanks, (2) owever it w rude oil and as started o	ed to other fit the damaged ontainment. 7 hk was also s 1000 bbl gu as holding m d produced v on 5/31/12 to	acilities. Fire crew containment. Two of the 1000 b everely damaged n barrels, and (1) tost some of the vater to travel off- determine the
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being r site into the p vertical and l	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to pasture. The porizontal es	containment. g responded to and Cleanup A ks were nearl 00 bbl fibergi uside the conta the damaged to affected area ktent of the sp	All of the o and had Action Ta y complet ass water ainment a tanks. The i in the pas bill. On 6/4	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh sture measured app 4/12 we began rem	mmedia 11:00 p er dispo to the l ere were ent was here the proxima noving	ately shut dow o.m. Vacuum sal tanks were ghtning hit ar a total of 4-1 damaged by containment ately 21,680 so the heavily im	n and incoming trucks started rer e located inside a d fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and b	streams noving v poly lin obl steel ss storag d fire; ho owing c event w nauling i	were divert vater from t ed metal cc oil skim tar e tanks, (2) owever it w rude oil and as started o t to an appr	ed to other fit the damaged ontainment. 7 hk was also s 1000 bbl gu as holding m d produced v n 5/31/12 to oved dispose	acilities. Fire crew containment. Two of the 1000 b everely damaged n barrels, and (1) tost some of the vater to travel off- determine the
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being r site into the p vertical and I The Site rem I hereby cert	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to pasture. The porizontal ex- ediation for ify that the i	containment. g responded to and Cleanup A ks were nearl 00 bbl fibergi uside the conta the damaged affected area ktent of the sp the produced nformation g	All of the o and had Action Ta y complet ass water ainment a tanks. The i in the pas bill. On 6/- water and iven abov	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh sture measured app 4/12 we began rem d crude oil spill wi e is true and comp	mmedia 11:00 p er dispo to the l ere were ent was here the proxima noving <u>II follo</u> lete to	ately shut dow o.m. Vacuum sal tanks were ghtning hit ar a total of 4-1 damaged by containment ately 21,680 se the heavily im w the NMOCI the best of my	n and incoming trucks started rer e located inside a d fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and b D and BLM guid knowledge and	streams noving v poly lin bbl steel ss storag d fire; hc owing c event w hauling i elines fo understa	were divert vater from t ed metal cc oil skim tar e tanks, (2) owever it w rude oil and as started o t to an appr r leaks and nd that pur	ed to other fit the damaged ontainment. ' nk was also s 1000 bbl gu as holding m d produced v or 5/31/12 to oved disposa spills. suant to NM	acilities. Fire crew containment. Two of the 1000 b reverely damaged n barrels, and (1) lost some of the vater to travel off- determine the al facility.
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being r site into the p vertical and I The Site rem I hereby cert regulations a	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to basture. The porizontal ex- ediation for ify that the i II operators	containment. g responded to and Cleanup A ks were nearl 00 bbl fibergi uside the conta the damaged affected area ktent of the sp the produced nformation g are required t	All of the o and had Action Ta y complet ass water ainment a tanks. The i in the pas bill. On 6/- water and iven abov to report a	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh sture measured app 4/12 we began rem d crude oil spill wi e is true and comp nd/or file certain r	mmedia 11:00 j er dispet to the l ere were ent was here the proxima hoving <u>ill follo</u> lete to elease n	ately shut dow o.m. Vacuum sal tanks were ghtning hit ar a total of 4-1 damaged by containment ately 21,680 so the heavily im w the NMOCI the best of my notifications a	n and incoming trucks started rer e located inside a d fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and b D and BLM guid knowledge and nd perform corre	streams noving v poly lin bbl steel ss storag d fire; he owing c event w nauling i elines fo understa ctive act	were divert vater from t ed metal cc oil skim tar e tanks, (2) owever it w rude oil and as started c t to an appr r leaks and nd that pur ions for rel	ed to other fit the damaged ontainment. The twas also so 1000 bbl gu as holding m d produced v on 5/31/12 to oved disposa spills. suant to NM eases which	acilities. Fire crev containment. Two of the 1000 b reverely damaged n barrels, and (1) lost some of the vater to travel off- determine the al facility. OCD rules and may endanger
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being r site into the p vertical and I The Site rem I hereby cert regulations a public health should their of	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to basture. The horizontal ex- ediation for ify that the i II operators or the enviro-	containment. g responded to and Cleanup A ks were nearl 00 bbl fibergi uside the conta the damaged affected area ktent of the sp the produced nformation g are required t ronment. The ave failed to	All of the o and had Action Ta y complet ass water ainment a tanks. The i in the pas bill. On 6/- water and iven abov to report a e acceptan adequatel	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh sture measured app 4/12 we began rem d crude oil spill wi e is true and comp nd/or file certain r ce of a C-141 report y investigate and r	mmedia 11:00 p er dispo- to the l ere were ent was here the proxima noving <u>ll follo</u> lete to elease p ort by th emedia	ately shut dow o.m. Vacuum sal tanks were ghtning hit ar a total of 4-1 damaged by containment ately 21,680 se the heavily im w the NMOCI the best of my notifications a a NMOCD m te contaminati	n and incoming trucks started rer e located inside a d fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and b D and BLM guid knowledge and nd perform corre arked as "Final I ton that pose a th	streams noving v poly lin bbl steel ss storag d fire; hc owing c event w nauling i elines fo understa ctive act Report" o reat to g	were divert vater from t ed metal cc oil skim tar e tanks, (2) owever it w rude oil and as started o t to an appr or leaks and nd that pur tions for rel does not rel round wate	ed to other fit the damaged ontainment. The twas also so 1000 bbl gu as holding m d produced v on 5/31/12 to oved disposa spills. Suant to NM eases which ieve the ope r, surface wa	acilities. Fire crew containment. Fwo of the 1000 b reverely damaged n barrels, and (1) lost some of the vater to travel off- determine the al facility. OCD rules and may endanger rator of liability ater, human health
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being of site into the p vertical and l The Site rem I hereby cert regulations a public health should their of or the enviro	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to basture. The horizontal ex- ediation for ify that the i II operators or the enviro- operations h nment. In a	containment. g responded to and Cleanup A ks were nearly 00 bbl fibergi uside the conta the damaged to affected area ktent of the sp the produced nformation g are required to ronment. The ave failed to ddition, NMC	All of the o and had Action Ta y complet ass water ainment a tanks. The i in the pas oill. On 6/4 water and iven abov to report a e acceptan adequatel DCD accep	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh sture measured app 4/12 we began rem d crude oil spill wi e is true and comp nd/or file certain r ce of a C-141 repo	mmedia 11:00 p er dispo- to the l ere were ent was here the proxima noving <u>ll follo</u> lete to elease p ort by th emedia	ately shut dow o.m. Vacuum sal tanks were ghtning hit ar a total of 4-1 damaged by containment ately 21,680 se the heavily im w the NMOCI the best of my notifications a a NMOCD m te contaminati	n and incoming trucks started rer e located inside a d fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and b D and BLM guid knowledge and nd perform corre arked as "Final I ton that pose a th	streams noving v poly lin bbl steel ss storag d fire; hc owing c event w nauling i elines fo understa ctive act Report" o reat to g	were divert vater from t ed metal cc oil skim tar e tanks, (2) owever it w rude oil and as started o t to an appr or leaks and nd that pur tions for rel does not rel round wate	ed to other fit the damaged ontainment. The twas also so 1000 bbl gu as holding m d produced v on 5/31/12 to oved disposa spills. Suant to NM eases which ieve the ope r, surface wa	acilities. Fire crew containment. Two of the 1000 b everely damaged n barrels, and (1) oost some of the vater to travel off- determine the al facility. OCD rules and may endanger rator of liability ater, human health
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being r site into the vertical and l The Site rem I hereby cert regulations a public health should their of	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to basture. The horizontal ex- ediation for ify that the i II operators or the enviro- operations h nment. In a	containment. g responded to and Cleanup A ks were nearly 00 bbl fibergi uside the conta the damaged to affected area ktent of the sp the produced nformation g are required to ronment. The ave failed to ddition, NMC	All of the o and had Action Ta y complet ass water ainment a tanks. The i in the pas oill. On 6/4 water and iven abov to report a e acceptan adequatel DCD accep	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh sture measured app 4/12 we began rem d crude oil spill wi e is true and comp nd/or file certain r ce of a C-141 report y investigate and r	mmedia 11:00 p er dispo- to the l ere were ent was here the proxima noving <u>ll follo</u> lete to elease p ort by th emedia	ately shut dow o.m. Vacuum sal tanks were ghtning hit ar a total of 4-1 damaged by containment ately 21,680 se the heavily im w the NMOCI the best of my notifications a a NMOCD m te contaminati	n and incoming trucks.started rer e located inside a ad fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and b D and BLM guid knowledge and nd perform corre arked as "Final H ton that pose a the re the operator of	streams noving v poly lin bbl steel ss storag d fire; hc lowing c event w hauling i elines fo understa ctive act Report" (reat to g `respons	were divert vater from t ed metal co oil skim tar e tanks, (2) owever it w rude oil and as started o t to an appr or leaks and nd that pur cions for rel does not rel round wate ibility for c	ed to other fit the damaged ontainment. The twas also so 1000 bbl gu as holding m d produced w on 5/31/12 to oved disposa spills. suant to NM eases which ieve the ope r, surface was	acilities. Fire crew containment. Two of the 1000 b everely damaged n barrels, and (1) tost some of the vater to travel off- determine the al facility. OCD rules and may endanger rator of liability tter, human health vith any other
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being or site into the p vertical and I The Site rem I hereby cert regulations a public health should their of or the enviro federal, state	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to basture. The horizontal ex- ediation for ify that the i II operators or the enviro- operations h nment. In a	containment. g responded to and Cleanup A ks were nearly 00 bbl fibergi uside the conta the damaged to affected area ktent of the sp the produced nformation g are required to ronment. The ave failed to ddition, NMC	All of the o and had Action Ta y complet ass water ainment a tanks. The i in the pas oill. On 6/4 water and iven abov to report a e acceptan adequatel DCD accep	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh sture measured app 4/12 we began rem d crude oil spill wi e is true and comp nd/or file certain r ce of a C-141 report y investigate and r	mmedia 11:00 p er dispo to the li- ere were ent was here the proxima noving ill follo lete to elease p ort by th emedia report o	ately shut dow o.m. Vacuum sal tanks were aghtning hit ar e a total of 4-1 damaged by i containment ately 21,680 so the heavily im withe NMOCI the best of my notifications a the NMOCD m te contaminati loes not reliev	n and incoming trucks.started rer e located inside a ad fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and b D and BLM guid knowledge and nd perform corre arked as "Final I ton that pose a th re the operator of OIL CON	streams noving v poly lin bbl steel ss storag d fire; hc owing c event w hauling i elines fo understa ctive act Report" (reat to g respons	were divert vater from t ed metal co oil skim tar e tanks, (2) owever it w rude oil and as started o t to an appr or leaks and nd that pur cions for rel does not rel round wate ibility for c	ed to other fit the damaged ontainment. In the was also so 1000 bbl gu as holding m d produced w on 5/31/12 to oved disposa spills. Suant to NM eases which ieve the ope r, surface was compliance w	acilities. Fire crew containment. Two of the 1000 b everely damaged n barrels, and (1) tost some of the vater to travel off- determine the al facility. OCD rules and may endanger rator of liability tter, human health vith any other
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being of site into the p vertical and l The Site rem I hereby cert regulations a public health should their of or the enviro	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to basture. The horizontal ex- ediation for ify that the i II operators or the enviro- operations h nment. In a	containment. g responded to and Cleanup A ks were nearly 00 bbl fibergi uside the conta the damaged to affected area ktent of the sp the produced nformation g are required to ronment. The ave failed to ddition, NMC	All of the o and had Action Ta y complet ass water ainment a tanks. The i in the pas oill. On 6/4 water and iven abov to report a e acceptan adequatel DCD accep	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh sture measured app 4/12 we began rem d crude oil spill wi e is true and comp nd/or file certain r ce of a C-141 report y investigate and r	mmedia 11:00 p er dispo to the li- ere were ent was here the proxima noving ill follo lete to elease p ort by th emedia report o	ately shut dow o.m. Vacuum sal tanks were aghtning hit ar e a total of 4-1 damaged by i containment ately 21,680 so the heavily im withe NMOCI the best of my notifications a the NMOCD m te contaminati loes not reliev	n and incoming trucks.started rer e located inside a ad fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and b D and BLM guid knowledge and nd perform corre arked as "Final I ton that pose a th re the operator of OIL CON	streams noving v poly lin bbl steel ss storag d fire; hc owing c event w hauling i elines fo understa ctive act Report" (reat to g respons	were divert vater from t ed metal co oil skim tar e tanks, (2) owever it w rude oil and as started o t to an appr or leaks and nd that pur cions for rel does not rel round wate ibility for c	ed to other fit the damaged ontainment. In the was also so 1000 bbl gu as holding m d produced w on 5/31/12 to oved disposa spills. Suant to NM eases which ieve the ope r, surface was compliance w	acilities. Fire crew containment. Two of the 1000 b everely damaged n barrels, and (1) tost some of the vater to travel off- determine the al facility. OCD rules and may endanger rator of liability tter, human health vith any other
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being or site into the p vertical and I The Site rem I hereby cert regulations a public health should their of or the enviro federal, state	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to basture. The horizontal ex- ediation for ify that the i II operators or the enviro operations h nment. In a or local law	containment. g responded to and Cleanup A ss were nearly 00 bbl fibergl uside the conta- the damaged to affected area stent of the sp the produced nformation g are required to addition, NMC ws and/or regu	All of the o and had Action Ta y complet ass water ainment a tanks. The i in the pas oill. On 6/4 water and iven abov to report a e acceptan adequatel DCD accep	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh sture measured app 4/12 we began rem d crude oil spill wi e is true and comp nd/or file certain r ce of a C-141 report y investigate and r	mmedia 11:00 p er dispo to the li- ere were ent was here the proxima noving ill follo lete to elease p ort by th emedia report o	ately shut dow o.m. Vacuum sal tanks were aghtning hit ar e a total of 4-1 damaged by i containment ately 21,680 so the heavily im withe NMOCI the best of my notifications a the NMOCD m te contaminati loes not reliev	n and incoming trucks.started rer e located inside a ad fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and b D and BLM guid knowledge and nd perform corre arked as "Final H ton that pose a th the the operator of <u>OIL CON</u> District Supervi Signed By	streams noving v poly lin bbl steel ss storag d fire; hc lowing c event w hauling i elines fo understa ctive act Report" (reat to g respons Strespons	were divert vater from t ed metal co oil skim tar e tanks, (2) owever it w rude oil and as started o t to an appr or leaks and nd that pur cions for rel does not rel round wate ibility for c	ed to other fit the damaged ontainment. In the was also so 1000 bbl gu as holding m d produced w on 5/31/12 to oved disposa spills. Suant to NM eases which ieve the ope r, surface was compliance w	acilities. Fire crew containment. Two of the 1000 b everely damaged n barrels, and (1) tost some of the vater to travel off- determine the al facility. OCD rules and may endanger rator of liability tter, human health vith any other
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being n site into the p vertical and I The Site rem I hereby cert regulations a public health should their of or the enviro federal, state	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to basture. The horizontal ex- ediation for ify that the i II operators or the enviro operations h nment. In a or local law e: Tony Sav	containment. g responded to and Cleanup A cs were nearly 00 bbl fibergl uside the conta- the damaged to affected area actent of the sp the produced nformation g are required to addition, NMC ws and/or regu	All of the o and had Action Ta y complet ass water ainment a tanks. The in the pas bill. On 6/- water and iven abov to report a e acceptan adequatel: DCD accepulations.	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh sture measured app 4/12 we began rem d crude oil spill wi e is true and comp nd/or file certain r ce of a C-141 report y investigate and r	mmedia 11:00 p er dispo to the li- ere were ent was here the proxima noving ill follo lete to elease p ort by th emedia report o	ately shut dow o.m. Vacuum sal tanks were aghtning hit ar e a total of 4-1 damaged by i containment ately 21,680 so the heavily im withe NMOCI the best of my notifications a the NMOCD m te contaminati loes not reliev	n and incoming trucks started rer e located inside a d fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and b D and BLM guid knowledge and nd perform corre arked as "Final H fon that pose a th the the operator of OIL CON District Supervi Signed By	streams noving v poly lin bbl steel ss storag d fire; hc lowing c event w hauling i elines fo understa ctive act Report" (reat to g respons SERV	were divert vater from t ed metal co oil skim tar e tanks, (2) owever it w rude oil and as started o t to an appr or leaks and nd that pur cions for rel does not rel round wate ibility for c	ed to other find the damaged to other find the damaged on the damaged on the damaged of the dama	acilities. Fire crew containment. Two of the 1000 b everely damaged n barrels, and (1) tost some of the vater to travel off- determine the al facility. OCD rules and may endanger rator of liability tter, human health vith any other
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being us site into the p vertical and I The Site rem I hereby cert regulations a public health should their of or the enviro federal, state Signature: Printed Nam	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to basture. The horizontal ex- ediation for ify that the i II operators or the enviro operations h nment. In a or local law e: Tony Sav	containment. g responded to and Cleanup A cs were nearly 00 bbl fibergl uside the conta- the damaged to affected area ktent of the sp the produced nformation g are required to addition, NMC ws and/or regured oie	All of the o and had Action Ta y complet ass water ainment a tanks. The in the pas bill. On 6/- water and iven abov to report a e acceptan adequatel: DCD accepulations.	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh sture measured app 4/12 we began rem d crude oil spill wi e is true and comp nd/or file certain r ce of a C-141 report y investigate and r	mmedia 11:00 p er dispo to the li- ere were ent was here the proxima noving ill follo lete to elease p ort by th emedia report o	Approval Da Conditions of Approval Da	n and incoming trucks started rer e located inside a ad fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and b D and BLM guid knowledge and nd perform corre arked as "Final I ton that pose a th te the operator of <u>OIL CON</u> District Supervi Signed By te:	streams noving v poly lin bbl steel s storag d fire; hc owing c event w nauling i elines fo understa ctive act Report" o reat to g respons VSERV	were divert vater from t ed metal cc oil skim tar e tanks, (2) owever it w rude oil and as started o t to an appr or leaks and nd that pur tions for rel does not rel round wate ibility for c	ed to other find the damaged to other find the damaged on the damaged on the damaged of the dama	acilities. Fire crew containment. Two of the 1000 bl everely damaged n barrels, and (1) tost some of the vater to travel off- determine the al facility. OCD rules and may endanger rator of liability tter, human health vith any other
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being is site into the p vertical and I The Site rem I hereby cert regulations a public health should their of or the enviro federal, state Signature: Printed Nam Title: Waste E-mail Addre	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to basture. The horizontal ex- ediation for ify that the i II operators or the enviro- perations h nment. In a or local law e: Tony Sav Mgmt.& Re	containment. g responded to and Cleanup A cs were nearly 00 bbl fibergl uside the conta- the damaged to affected area ktent of the sp the produced nformation g are required to addition, NMC ws and/or regu- oie mediation Sp bie@BassPet.	All of the o and had Action Ta y complete ass water ainment a tanks. The in the pas oill. On 6/- water and iven abov to report a e acceptan adequatel: DCD accep ulations.	e production was in the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme are were 3 areas wh sture measured app 4/12 we began rem d crude oil spill wi e is true and comp nd/or file certain r ce of a C-141 report y investigate and r	mmedia 11:00 p er dispo to the li- ere werd ent was here the proxima noving ill follo lete to elease p ort by th emedia report o	Approval Da Conditions of Remediat	n and incoming trucks.started rer e located inside a ad fire. The 500 k 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and k D and BLM guid knowledge and nd perform corre arked as "Final k ton that pose a th te the operator of <u>OIL CON</u> District Supervi Signed By JUN 2 ? te:	streams noving v poly lin bbl steel ss storag d fire; hc lowing c event w hauling i elines fo understa ctive act Report" (reat to g respons Sor: 2012 Rules 8 DIATIC	were divert vater from t ed metal co oil skim tar e tanks, (2) owever it w rude oil and as started o t to an appr or leaks and nd that pur cions for rel does not rel round wate ibility for co <u>ATION</u> Expiration	ed to other fitthe damaged ontainment. The was also so 1000 bbl gu as holding m d produced v on 5/31/12 to oved disposa spills. Suant to NM eases which ieve the ope r, surface wa compliance v DIVISIC	acilities. Fire crew containment. Two of the 1000 bl everely damaged n barrels, and (1) tost some of the vater to travel off- determine the al facility. OCD rules and may endanger rator of liability tter, human health vith any other
adjacent tank from Malaga Describe Are fiberglass gu along with or 500 bbl. Oil water being u site into the vertical and U The Site rem I hereby cert regulations a public health should their or the enviro federal, state Signature: Printed Nam Title: Waste E-mail Addre	as inside the and Loving a Affected a n barrel tank ne of the 100 skim tank in released by to basture. The horizontal ex- ediation for ify that the i II operators or the enviro- perations h nment. In a or local law e: Tony Sav Mgmt.& Re	containment. g responded to and Cleanup A cs were nearly 00 bbl fibergl uside the conta- the damaged to affected area ktent of the sp the produced nformation g are required to addition, NMC ws and/or regu- oie mediation Sp bie@BassPet.	All of the o and had Action Ta y complete ass water ainment a tanks. The in the pas oill. On 6/- water and iven abov to report a e acceptan adequatel: DCD accep ulations.	e production was i the fire put out by ken.*The salt wate ely destroyed due storage tanks. The rea. The containme re were 3 areas wi sture measured app 4/12 we began ren 1 crude oil spill wi e is true and comp nd/or file certain r ce of a C-141 report y investigate and r obtance of a C-141	mmedia 11:00 p er dispo to the li- ere werd ent was here the proxima noving ill follo lete to elease p ort by th emedia report o	Approval Da Conditions of Remediat	n and incoming trucks started rer e located inside a ad fire. The 500 b 000 bbl fiberglas falling piping and was breached all q. ft. A sampling pacted soil and b D and BLM guid knowledge and nd perform corre arked as "Final I ton that pose a th te the operator of <u>OIL CON</u> District Supervi Signed By te:	streams noving v poly lin bbl steel ss storag d fire; hc lowing c event w hauling i elines fo understa ctive act Report" (reat to g respons Sor: 2012 Rules 8 DIATIC	were divert vater from t ed metal co oil skim tar e tanks, (2) owever it w rude oil and as started o t to an appr or leaks and nd that pur cions for rel does not rel round wate ibility for co <u>ATION</u> Expiration	ed to other fitthe damaged ontainment. The was also say the damaged ontainment. The was also say the damaged ontainment. The was also say the dispose over dispose say the dispose say the dispose summer of the dispose say t	acilities. Fire crew containment. Two of the 1000 b everely damaged n barrels, and (1) tost some of the vater to travel off- determine the al facility. OCD rules and may endanger rator of liability tter, human health vith any other
