Diament I				<b>2</b>			F	REC	EIV	ED
<u>District I</u> 1625 N French Dr., Hobbs, NM 88240				New Mexi and Natural		JUL	<b>26</b> 20	12 Revised Octobe		
District II 1301 W. Grand District III	Avenue, Arti	esia, NM 8821(	)				· · · · · · · · · · · · · · · · · · ·			
1000 Rio Biazo District IV	is Road, Azte	c, NM 87410			Oil Conservation Division 1220 South St. Francis Dr. NMOCD ARTESIA				ESIArict Office in ac with Rule 11	
	acis Dr., Santa	a Fe, NM 8750.	5			e, NM 875				sid
	*****		Rel	ease Notifica	tior	1 and Co	rrective A	ction		
	12215					OPERAT			🛛 Inita	al Report 🗌 Fin
Name of C Address				IG LLC <b>22913</b> dland, TX 79701	-T	Contact Telephone N		at Ellis 230-007	7	
Facility Na		Lightning 2				Facility Type		k Batter		
Surface Ow	mer Fede	ra]		Mineral Ow	ner				Lease N	lo. (API#) 30-015-3
				LOCAT	'IOI	N OF REL	EASE			
Unit Letter B	Section 24	Township 25S	Range 26E			South Line	Feet from the	East/W	est Line	County Eddy
	.1	1	.]	Latitude 32 07.	270	Longitu	ide 104 14.667	I		
	-					OF RELI				
Type of Rele						Volume of Release 100bbls Volume Recovered 80bbls				
Source of Re	lease Steel	l tank				Date and H 07/11/2012	our of Occurrenc			Hour of Discovery 2 2:30 p.m.
Was Immedi	ate Notice (		Ves [	] No 🗌 Not Requ	uired	If YES, To	Whom?	Mike B	ratcher-O	חר חר
								Jim A	mos-BLM	1
By Whom?	Michelle N	Aullins				Date and Hour 07-11/2012 7.53 p.m.				
Was a Water	course Read		Yes 🗵	] No		If YES, Volume Impacting the Watercourse.				
If a Waterco	urse was Im	pacted, Descr								
		em and Reme								***
for repairs.					luids	inside the fac	ility. The tank ha	as been ta	aken out o	f service, cleaned, and
Describe Are	a Affected a	and Cleanup /	Action Tal	(en.*			,			
recovered. T	he release w	vas completely	y containe	d inside the dike wal	ls of 1	the facility T	etra Tech will sai	mple the	spill site a	ck. All free fluid has b trea to delineate any po significant remediatio
regulations a public health should their o or the enviro	II operators is or the enviroperations his nment. In a	are required t ronment. The lave failed to a	o report al e acceptane adequately DCD accept	nd/or file certain rele ce of a C-141 report investigate and rem	ase n by the ediate	otifications an e NMOCD ma e contaminatio	d perform correc arked as "Final Roon that pose a three	tive action eport <sup>®</sup> do eat to gro	ons for reli bes not reli bund water	uant to NMOCD rules cases which may endar eve the operator of hal r, surface water, human compliance with any oth
		7- 1	$\square$	` <u> </u>	_		OIL CON	SERV	ATION	DIVISION
Signature:		Josh	RUSSO	ノ		Approved by I	District Supervise	or.	Signed I	By Mily Bren
Signature: Printed Name	<u>~.</u>					۸۸	UG 0 2 201	9 г		
		HSE C	oordinator			Approval Dat	OO OF PAI	<b>C</b> a	xpiration	Date:
Printed Nam		HSE C				Approval Data			xpiration	·
Printed Name Title: E-mail Addre Date.	ess: )7/26/2012		e. 432					<u>(ca)   1</u>		Attached  2RP-

.

From:	Joshua Russo <jrusso@concho.com></jrusso@concho.com>
Sent:	Thursday, July 26, 2012 2:46 PM
То:	Bratcher, Mike, EMNRD; Jim Amos office (jamos@blm.gov); Gregston, Terry G
Cc:	Tavarez, Ike; Dorey, Kim; Franklin, Tom K.
Subject:	C-141 Initial Report - Lightning 24 Federal Com #1 TB
Attachments:	LIGHTNING 24 FEDERAL COM #1 TANK BATTERY DATE OF RELEASE
	07-11-2012.pdf

Please see attached a C-141 Initial Report for a release that occurred at our Lightning 24 Federal Com #1 TB. We plan to assess the spill area timely.

Thank you,

# Joshua Russo

HSE Coordinator 550 W. Texas Ave, Suite 100 Midland, Texas 79701 Phone: (432) 683-7443 Cell: (432) 212-2399 irusso@conchoresources.com

13

From:	Michelle Mullins [MMullins@concho.com]
Sent:	Wednesday, July 11, 2012 6:53 PM
То:	Bratcher, Mike, EMNRD; Amos, James A; Gregston, Terry G
Cc:	Joshua Russo
Subject:	Lightning 24 Fed Com #1-Immediate Notification

Mr. Bratcher, Mr. Amos, Ms. Gregston

On 7-11-12 at approximately 2:30pm, a produced water leak was discovered at the Lightning 24 Fed Com #1 tank battery. The produced water storage tank had developed a hole. An estimated 100bbls of produced water was released. 80 bbls were recovered from inside the unlined dike by vacuum truck. The tank has been removed from service and is awaiting repair. We will get more details and follow up with a C-141 Report.

GPS coordinates, legal description, and driving directions below.

GPS-unavailable at report time

Lightning 24 Fed Com #1 660'FNL & 1980'FEL Sec. 24, T25S, R<del>36E</del> Eddy Co. API 30-015-33001

On Old Cavern Highway, travel south till Black River Village Road. Cross it. Road becomes John D. Forham. Travel approximately 8.2 miles, turn right into location.

Thank you,

Michelle Mullins HSE Field Tech 2407 Pecos Avenue P.O. Box 1630 Artesia, NM 88211-1630 Phone: (575)746-2010 Cell: (432) 934-1052 mmullins@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From:	Amos, James A [jamos@blm.gov]
Sent:	Thursday, July 12, 2012 8:19 AM
То:	Michelle Mullins; Bratcher, Mike, EMNRD; Gregston, Terry G
Cc:	Joshua Russo
Subject:	RE: Lightning 24 Fed Com #1-Immediate Notification

Michelle,

Thanks for the notification, I'll be the contact on this one.

From: Michelle Mullins [mailto:MMullins@concho.com]
Sent: Wednesday, July 11, 2012 6:53 PM
To: mike.bratcher@state.nm.us; Amos, James A; Gregston, Terry G
Cc: Joshua Russo
Subject: Lightning 24 Fed Com #1-Immediate Notification

Mr. Bratcher, Mr. Amos, Ms. Gregston

On 7-11-12 at approximately 2:30pm, a produced water leak was discovered at the Lightning 24 Fed Com #1 tank battery. The produced water storage tank had developed a hole. An estimated 100bbls of produced water was released. 80 bbls were recovered from inside the unlined dike by vacuum truck. The tank has been removed from service and is awaiting repair. We will get more details and follow up with a C-141 Report.

GPS coordinates, legal description, and driving directions below.

GPS-unavailable at report time

Lightning 24 Fed Com #1 660'FNL & 1980'FEL Sec. 24, T25S, R36E Eddy Co. API 30-015-33001

On Old Cavern Highway, travel south till Black River Village Road. Cross it. Road becomes John D. Forham. Travel approximately 8.2 miles, turn right into location.

Thank you,

Michelle Mullins HSE Field Tech 2407 Pecos Avenue P.O. Box 1630 Artesia, NM 88211-1630 Phone: (575)746-2010 Cell: (432) 934-1052 mmullins@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review,

dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Sent: To: Cc:	Michelle Mullins [MMullins@concho.com] Thursday, July 12, 2012 8:27 AM 'jamos@blm.gov'; Bratcher, Mike, EMNRD; 'tgregsto@blm.gov' Joshua Russo
Subject:	Re: Lightning 24 Fed Com #1-Immediate Notification
Thanks Jim.	
Michelle Mullins	
HSE Field Tech	
2407 Pecos Avenue	
P.O. Box 1630	
Artesia, NM � 88211-163	C
Phone: (575)746-2010	
Cell: (432) 934-1052	
mmullins@conchoresource	es.com �
CONFIDENTIALITY NOTICE:	The information in this email may be confidential and/or privileged. $\boldsymbol{\$}$ If y

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Amos, James A [mailto:jamos@blm.gov]
Sent: Thursday, July 12, 2012 09:19 AM
To: Michelle Mullins; mike.bratcher@state.nm.us <mike.bratcher@state.nm.us>; Gregston, Terry G <tgregsto@blm.gov>
Cc: Joshua Russo
Subject: RE: Lightning 24 Fed Com #1-Immediate Notification

Michelle,

Thanks for the notification, I'll be the contact on this one.

From: Michelle Mullins [mailto:MMullins@concho.com]
Sent: Wednesday, July 11, 2012 6:53 PM
To: mike.bratcher@state.nm.us; Amos, James A; Gregston, Terry G
Cc: Joshua Russo
Subject: Lightning 24 Fed Com #1-Immediate Notification

#### Mr. Bratcher, Mr. Amos, Ms. Gregston

On 7-11-12 at approximately 2:30pm, a produced water leak was discovered at the Lightning 24 Fed Com #1 tank battery. The produced water storage tank had developed a hole. An estimated 100bbls of produced water was released. 80 bbls were recovered from inside the unlined dike by vacuum truck. The tank has been removed from service and is awaiting repair. We will get more details and follow up with a C-141 Report.

GPS coordinates, legal description, and driving directions below.


GPS-unavailable at report time

Lightning 24 Fed Com #1 660'FNL & 1980'FEL Sec. 24, T25S, R36E Eddy Co. API 30-015-33001

On Old Cavern Highway, travel south till Black River Village Road. Cross it. Road becomes John D. Forham. Travel approximately 8.2 miles, turn right into location.

Thank you,

Michelle Mullins HSE Field Tech 2407 Pecos Avenue P.O. Box 1630 Artesia, NM 88211-1630 Phone: (575)746-2010 Cell: (432) 934-1052 mmullins@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.