

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
**HOBBS OGD** Oil Conservation Division  
Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

NOV 13 2012  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company- NADEL AND GUSSMAN HEYCO, LLC	Contact Larry Brigance or Tammy R. Link
Address P.O. Box 1936, Roswell, NM 88202-1936	Telephone No. (575)623-6601
Facility Name Pearsall 6 Federal #11	Facility Type

Surface Owner USA	Mineral Owner State of New Mexico	API No.30-025-39487
-------------------	-----------------------------------	---------------------

**LOCATION OF RELEASE**

Unit Letter P	Section 6	Township 18S	Range 32E	Feet from the 660'	North/South Line S	Feet from the 990'	East/West Line E	County Lea
------------------	--------------	-----------------	--------------	-----------------------	-----------------------	-----------------------	---------------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release - oil	Volume of Release - 20 bbls	Volume Recovered - 18 bbls
Source of Release - Tank	Date and Hour of Occurrence 11/6/12 12:00	Date and Hour of Discovery - 11/7/12 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*

N/A

G.W @ 225'



Describe Cause of Problem and Remedial Action Taken.\*

Fire Tube Gasket blew. Crew is out to repair and return to production.

Describe Area Affected and Cleanup Action Taken.\*

Spill 3-7 bbls on location and 10-13 bbls inside Heater Dike, removed 4 bbls of oil off ground and recovered 14 out of the dike near heater.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: TAMMY R. LINK	Approved by Environmental Specialist  Environmental Specialist	
Title: Production Analyst	Approval Date: 11/13/12	Expiration Date: 01/14/13
E-mail Address: tlink@heycoenergy.com	Conditions of Approval: DELINEATE HORIZONTALLY AND VERTICALLY, REMEDIATE TO NMOCD RRALS.	
Date: 11/8/12 Phone: (575)623-6601	Attached <input type="checkbox"/> IRP-11-12-2866	

\* Attach Additional Sheets If Necessary

SUBMIT FINAL C-141 TO  
NMOCD BY 01/14/13.

NOV 14 2012