District 1 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Sanja Fe, NM 87505

Name of Company

State of New Mexico

Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

HOBBS OCD

Form C-141 Revised October 10, 2003

Final Report

RE	CEIVED	side of form
		with Rule 116 on back
	_	District Office in accordance
	ST ST	ubmit 2 Copies to appropriate
UEU	0 4 2012	ubmit 2 Copies to appropriate District Office in accordance
n ~ ^	~ / ~ ~ ~	1001300-00000110, 200

	an marth a stairthairtha		
OPER	ATOR	\boxtimes	Initial Report
 OGRID Number	Contact		
25575	Lupe Carrasco		

Yates Petroleum Corporation	25575	Lupe Carrasco		
Address		Telephone No.		
104 S. 4 TH Street		575-748-1471		
Facility Name	API Number	Facility Type		
Cleary Federal SWD #2	30-025-31926	Battery		
Surface Owner	Mineral Own	۵ ۲	Lease No.	
	1			
Federal	Federal		NM-86148	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
, D	17	228	32E	330	North	330	West	Lea
								L

Latitude 32.6081700 Longitude 104.53856

NATURE OF RELEASE						
Type of Release	Volume of Release	Volume Recovered				
Crude Oil and Produced Water	90 B/O; 500 B/PW	530 B/O&PW				
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery				
Static Electricity	11/28/2012 PM	11/28/2012 PM				
Was Immediate Notice Given?	If YES, To Whom? Geoffrey Leking, NMOCD I					
By Whom? Amanda Trujillo, Yates Petroleum Corporation	Date and Hour 11/28/2012 PM (email)					
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.					
Yes X No	N/A					
If a Watercourse was Impacted, Describe Fully.*						
Describe Cause of Problem and Remedial Action Taken.* A fire was reported by a nearby drilling rig. Emergency crew responded to the seen. Possible static electricity started the fire. The fire and all lost fluid were contained within the berm. The berm was lined and maintained its integrity throughout the incident. Vacuum trucks dispatched to recover standing fluid.						
Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 120' was impacted. The secondary contain fluid. Due to the nature of the fire and the damaged equipment, all metal secondary containment and disposed of at an NMOCD approved facility. Water: >100' (approximately 240', Section 17-T22S-R32E, per Trend >1000', SITE RANKING IS 0.	within the berm will be scrapped. So YPC will construct a new facility in	il and gravel will be removed from the place of the old one. Depth to Ground				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						
Signature: The Course of the Sector Sector Sector						
Printed Name: Lupe Carrasco Approved by District Supervisor: Environmental Specialist						
Title: Environmental Regulatory Agent	Approval Date: 12/04/12 Expiration Date: -					
E-mail Address: Icarrasco@yatespetrolcum.com	Conditions of Approval:	Attached 🔲				
Date: Tuesday, December 04, 2012 Phone: 575-748-1471	2RP-	IRP-12-12-2877				

* Attach Additional Sheets If Necessary

DEC 0 5 2012