


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-14  
Revised August 8, 20  
Submit a Copy to appropriate District Office  
according with 19.15.29 NMAI

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	DCP Midstream, LP	36785	Contact	Jon Bebbington
Address	10 Desta Drive, Suite 400 West		Telephone No.	432-620-4207
Facility Name	MM Gas Pipeline		Facility Type	Gas Pipeline

Surface Owner	BLM	Mineral Owner		API No.	
---------------	-----	---------------	--	---------	--

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	21	17S	31E					EDDY

Latitude 32.819780

Longitude -103.866746

#### NATURE OF RELEASE

Type of Release	Crude & Raw Natural Gas	Volume of Release	60 bbl	Volume Recovered	40 bbl
Source of Release	MM Gas Pipeline	Date and Hour of Occurrence	unknown	Date and Hour of Discovery	10-22-2012 0900
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required				
By Whom?	Jon D. Bebbington	If YES, To Whom? Jim Amos/BLM via email, Carl Chavez/OCD via voicemail, Geoffrey R. Leking/OCD Hobbs via telephone			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Date and Hour 10-22-2012 1600		
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.\* N / A

Describe Cause of Problem and Remedial Action Taken.\*

DCP's MM gas pipeline was discovered to have burst in two separate locations 1500 feet apart. Crude oil spilled from the failure points and ran down a lease road. The probable cause is an overpressure followed by rupture at two corroded locations.

Describe Area Affected and Cleanup Action Taken.\*

DCP's MM gas pipeline was discovered to have burst in two separate locations 1500 feet apart and 4 feet deep. Raw natural gas was released as well as approx. 60 bbls of crude that had entered the line from a producer. The two impacted areas are almost totally within the confines of a dirt lease road running in an east to west direction. The crude oil flowed west from each of the two release points. Bids are being obtained from cleanup contractors and once a selection is made a cleanup plan will be submitted to BLM for review and approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Jon D. Bebbington		Signed By:	
Title: Sr. Environmental Engineer		Approved by Environmental Specialist:	
E-mail Address: jdbbebbington@dcpmidstream.com		Approval DEC 04 2012	
Date: 10-26-2012 Phone: 432-620-4207		Expiration Date:	
		Conditions of Approval:	
		Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 1/4/2013	
		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

f MLCB 1233957423

v - MLCB 1234025497

n MLCB 1233957652

i MLCB 1234025434

2RP-1433

## Bratcher, Mike, EMNRD

---

**From:** Leking, Geoffrey R, EMNRD  
**Sent:** Friday, October 26, 2012 11:48 AM  
**To:** Bebbington, Jon D  
**Cc:** Bratcher, Mike, EMNRD  
**Subject:** RE: C-141 Initial Report - MM Line Spill near Loco Hills, NM

Jon

Using the longitude and latitude coordinates you provided on the C-141 (no legals provided), I found the release point to be in Eddy County which is in District 2. Please contact Mike Bratcher of that office. I will forward your email that has the C-141 attached to him. Please contact me if you find my observation to be in error. Thank you.

Geoffrey Leking  
Environmental Specialist  
NMOCD-Hobbs  
1625 N. French Drive  
Hobbs, NM 88240  
Office: (575) 393-6161 Ext. 113  
Cell: (575) 399-2990  
email: [geoffreyr.leking@state.nm.us](mailto:geoffreyr.leking@state.nm.us)

---

**From:** Bebbington, Jon D [<mailto:JDBebbington@dcpmidstream.com>]  
**Sent:** Friday, October 26, 2012 11:00 AM  
**To:** Leking, Geoffrey R, EMNRD; Brumley, Legion; Dade, Randy, EMNRD  
**Cc:** Case, Nicholas L; Ortega, Russell G; Mendenhall, Quentin; Grajeda De Babb, Patricia; Drannon, Perry G  
**Subject:** C-141 Initial Report - MM Line Spill near Loco Hills, NM

Please find the attached initial C-141 report for the release that occurred early this week near Loco Hills, NM. DCP is currently obtaining bids for remediation of impacted areas. Once a selection is made, a work plan will be developed and submitted for your approval.

*Jon Bebbington*  
*Senior Environmental Specialist*  
*Permian Region*

*DCP Midstream, LP*  
*10 Desta Drive, Suite 400 West*  
*Midland, TX 79705*  
*Ofc: 432-620-4207*  
*Cell: 432-413-3601*  
*e-mail: [jdbebbington@dcpmidstream.com](mailto:jdbebbington@dcpmidstream.com)*

