

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

NOV 07 2012

Form C-141  
Revised August 8, 2011

Submit 1/ Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJM/N1231341442 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: Chevron	241333	Contact: Ms. Donna Burt
Address: 2401 Avenue O, P.O. Box 1949, Eunice, NM 88231		Telephone No.: (575) 631-2151
Facility Name: Pardue Farms 27-12		Facility Type: Oil Well

Surface Owner: Billy Melton	Mineral Owner: Chevron	API No. 30-015-28980
-----------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter 12 K	Section 27	Township 23 S	Range 28 W	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
---------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.27358 Longitude W 104.07818

NATURE OF RELEASE

Type of Release: Produced water with oil.	Volume of Release: Initial estimate of 3.617 bbls.	Volume Recovered: None.
Source of Release: Flowline	Date and Hour of Occurrence: May 2010	Date and Hour of Discovery: June 7, 2010, 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* No impact to a watercourse occurred.		

Describe Cause of Problem and Remedial Action Taken.\*

Flowline had a pin hole on the top side of the pipe caused by internal corrosion. The leak was stopped upon discovery and a subcontractor was called to remediate impacted soil and replace the flowline. The release was initially estimated at less than 5 bbls and an internal report was produced.

Describe Area Affected and Cleanup Action Taken.\*

The area surrounding the pin hole on the flow line appeared wet. A subcontractor was called to remediate the impacted soil and replace the flow line. The contractor excavated some impacted soil. However once excavation began it appeared that the release was greater than 5 bbls. Two boreholes were drilled that indicated that the release may be larger than 5 bbls. The exact amount of fluid lost has not been determined.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCID rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCID marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCID acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Bo y J. Hill

Title: Production Team Leader

E-mail Address: bobyhill@chevron.com

Date: 11/7/12

Phone: 575-631-9108

Approved by Environmental Specialist:

Signed By: [Signature]

Approval Date: NOV 08

Expiration Date:

Conditions of Approval:

Attached ☐

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:

Dec. 8, 2012

2RP-1395

## **Bratcher, Mike, EMNRD**

---

**From:** Bockisch, Bernie <bbockisch@croworld.com>  
**Sent:** Wednesday, November 07, 2012 1:54 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Burt, Donna T (DonnaBurt); Larson, Thomas  
**Subject:** Pardue Farms C-141 Form  
**Attachments:** Pardue Farms C-141.pdf

Mike,

As discussed, I am submitting the C-141 Form on behalf of Chevron USA, Inc. Could you please provide me with a RP number for this when you get a chance. Thanks and please feel free to contact me if you have any questions.

Bernie

**Bernard Bockisch, PMP**  
**Conestoga-Rovers & Associates (CRA)**

6121 Indian School Rd NE Ste. 200

Albuquerque, NM, USA 87110

Office: (505) 884-0672

Mobile: (505) 280-0572

Fax: (505) 884-4932

Email: [bbockisch@croworld.com](mailto:bbockisch@croworld.com)

[www.CRAworld.com](http://www.CRAworld.com)

## Bratcher, Mike, EMNRD

---

**From:** Bratcher, Mike, EMNRD  
**Sent:** Wednesday, November 07, 2012 3:00 PM  
**To:** 'Bockisch, Bernie'  
**Cc:** Burt, Donna T (DonnaBurt); Larson, Thomas  
**Subject:** RE: Pardue Farms C-141 Form

Bernie,

It will be 2RP-1395, but may be a couple of days before it gets entered in the system.

Thanks,

Mike Bratcher  
NMOCD District 2  
811 S. First Street  
Artesia, NM 88210  
O: 575-748-1283 X108  
C: 575-626-0857  
F: 575-748-9720

---

**From:** Bockisch, Bernie [<mailto:bbockisch@craworld.com>]  
**Sent:** Wednesday, November 07, 2012 1:54 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Burt, Donna T (DonnaBurt); Larson, Thomas  
**Subject:** Pardue Farms C-141 Form

Mike,

As discussed, I am submitting the C-141 Form on behalf of Chevron USA, Inc. Could you please provide me with a RP number for this when you get a chance. Thanks and please feel free to contact me if you have any questions.

Bernie

**Bernard Bockisch, PMP**  
**Conestoga-Rovers & Associates (CRA)**  
6121 Indian School Rd NE Ste. 200  
Albuquerque, NM, USA 87110  
Office: (505) 884-0672  
Mobile: (505) 280-0572  
Fax: (505) 884-4932  
Email: [bbockisch@craworld.com](mailto:bbockisch@craworld.com)  
[www.CRAworld.com](http://www.CRAworld.com)