


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

JMW 1322730497 OPERATOR ☐ Initial Report ☒ Final Report

| | | | |
|------------------|--|----------------|--------------|
| Name of Company: | Enterprise Products LLC 1000347 | Contact: | Jim Heap |
| Address: | PO Box 4324, Houston, TX 77252 | Telephone No.: | 432-686-5404 |
| Facility Name: | Pipeline #1009 E | Facility Type: | Pipeline |
| Surface Owner | Mineral Owner | API No. | |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| | 28 | 22S | 30E | | | | | Eddy |

Latitude: 32.361513 Longitude: -103.893474

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release: Natural Gas | Volume of Release: 849 Mcf | Volume Recovered: 0 |
| Source of Release: Section blow-down to repair a valve | Date and Hour of Occurrence: 19MAR2012 @ 09:00 MDT | Date and Hour of Discovery: 19MAR2012 @ 08:30 MDT |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Region 2 OCD by phone | |
| By Whom? Jim Heap | Date and Hour: 20MAR2012 @ 06:30 MDT | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* CAUSE: A valve began leaking after being lubricated. ACTION: The line was blocked-in and blown down. The grease fitting (zirk) was replaced. | | |
| Describe Area Affected and Cleanup Action Taken.* All gas was lost to atmosphere. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature: | OIL CONSERVATION DIVISION | |
| Printed Name: Matthew E. Marra | Approved by Environmental Specialist: Accepted for record NMOCD | |
| Title: Senior Director - Environmental | Approval Date: AUG 15 2013 | Expiration Date: |
| E-mail Address: memarra@eprod.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 3/20/2012 Phone: 713-381-6684 | | |

* Attach Additional Sheets If Necessary

JMW 1322730449


JMW 1322730737

2RP-1828



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC



March 20, 2012

Return Receipt Requested
7011 3500 0000 4128 9861

Mr. Mike Bratcher
District Supervisor
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report of Gas Loss, Line 1009 Valve Repair
Enterprise Products LLC**

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC, Enterprise Products LLC is submitting the required C-141 Form for an 849 MCF release from our Line 1009 in Eddy County on March 19, 2012. The line section was blown-down to repair a leaking valve fitting (zirk). Verbal notification was made to your office on March 20, 2012.

If you have any questions or need additional information, please contact our area field representative, Jim Heap, at 432-696-5404 (jkheap@eprod.com) or me directly at 713-381-6684.

Yours truly,

Matthew E. Marra
Sr. Director – Environmental & Technical Services

/bjm
attachments