

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

State of New Mexico

Energy Minerals and Natural Resources

SEP 12 2013

Oil Conservation Division

1220 South St. Francis Dr.

RECEIVED

Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Cimarex Energy Co	Contact	Mark Bishop
Address	2020 West Bender, Hobbs	Telephone No.	575-602-1002
Facility Name	N Maduro Fed Unit #3H	Facility Type	Oil Production

Surface Owner	BLM	Mineral Owner	BLM	API No.	30-025-39623
---------------	-----	---------------	-----	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	20	19S	33E	2310'	FNL	560'	FWL	Lea

20RL
9/18/13

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	2-3 bbl	Volume Recovered	0
Source of Release	Tubing	Date and Hour of Occurrence	9-11-13 2:00PM	Date and Hour of Discovery	9-11-13 2:30 PM

Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?
---	------------------

By Whom?	Mark Bishop	Date and Hour	9-11 2:30 PM
----------	-------------	---------------	--------------

Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.
---	---

If a Watercourse was Impacted, Describe by: <i>Jeffrey Sekins</i> Environmental Specialist 9/18/13 GW @ 195'
--

Describe Cause of Problem and Remedial Action Taken.* Polished Rod on pumping unit broke; lower portion of polished rod fell back inside tubing allowing fluid to pass through open stuffing box. Oil squirted straight up into air and was carried by wind across location painting 40' X 150' area of well pad location with oil. There was no standing oil to pick up.
--

Describe Area Affected and Cleanup Action Taken.* 40' X 150' area of location was superficially oil stained. There was no standing oil to pick up. Used roustabouts and backhoe to scrape surface of caliche pad and heavier affected area around wellhead was shoveled into bucket and loaded into dump truck and taken to approved disposal facility.
--

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
--

Signature: Mark Bishop	OIL CONSERVATION DIVISION	
Printed Name: Mark Bishop	Approved by Environmental Specialist: <i>Jeffrey Sekins</i> Environmental Specialist	
Title: Production Foreman	Approval Date: 9/18/13	Expiration Date: 11/18/13
E-mail Address: mbishop@cimarex.com	Conditions of Approval: DELINQUENT REMEDIAL PER NMOCD GUIDELINES SUBMIT FINAL C-141 BY _____	
Date: 9-12-13 1002	Phone: 575-602-1002	Attached <input type="checkbox"/> IRP-9-13-2960

SEP 23 2013

Attach Additional Sheets If Necessary

HOBBS OCD

SEP 12 2013

RECEIVED