


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

JMW 1325536299

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Big Eddy Unit 33 Tank Battery	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-20369
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 4	Township 20S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------

Latitude N 32.596782 Longitude W 103.86772

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 80 Bbls	Volume Recovered: 60 Bbls
Source of Release: 4" truck load line	Date and Hour of Occurrence: 8/21/13, Time unknown	Date and Hour of Discovery: 8/21/13 Time 11:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour 8/21/13 at 5:40 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The truck loaded developed a leak due to internal corrosion, the tank valve was shut and the load line was replaced.

Describe Area Affected and Cleanup Action Taken.*
The spill stayed inside the earthen containment around the tank location, the bermed area measured approximately 30 ft. by 55 ft. Approximately 1650 sq. ft. of containment area was impacted by the release. All of the free product was removed at the time of discovery. A remediation plan will be submitted to the NMOCD. The remediation will comply with the NMOCD and BLM guidelines for spill remediation

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: Signed By <i>Mike Brannon</i>	
Title: Waste Management and Remediation Specialist		Approval Date: SEP 11 2013	Expiration Date:
E-mail Address: tasavoie@basspet.com		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	
Date: 9/10/13 Phone: 432-556-8730		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
October 11, 2013

2RP-1905