

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1329439653 OPERATOR ☐ Initial Report ☒ Final Report

Name of Company OXY USA WTP LP <i>16696</i>	Contact CAMPBELL, RODNEY	
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4167	
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING FACILITY	
Surface Owner	Mineral Owner INDIAN BASIN	Lease No.

LOCATION OF RELEASE


Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 165 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 4/18/2013 6:22:00 AM	Date and Hour of Discovery 4/18/2013 6:22:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

Cause:
IBGP FLARED RESIDUE SALES GAS THREE TIMES FOR A TOTAL OF 27 MINUTES.
Remedial Action Taken:
OPERATIONS SAMPLED INLET GATHERING LINE FOR EXCESSIVE O2. OPERATIONS NOTIFIED FIELD PRODUCTION COORDINATOR, HE SAID HE WAS UNAWARE OF ANY WELLS BEING PUT ONLINE BUT WOULD CHECK INTO IT. DUE TO THE SHORT DURATION OF THE FLARE EVENTS THE SOURCE OF O2 COULDN'T BE DETERMINED. 1ST EVENT 3:58 pm - 4:01 pm, 2ND EVENT 6:22 pm - 6:41 pm, 3RD EVENT 7:19 pm - 7:24 pm.

Describe Area Affected and Cleanup Action Taken.*
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>	OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL	Accepted for record NMOCD	
Title: <i>HES Specialist</i>	Approval Date: OCT 21 2013	Expiration Date:
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>7-23-13</i> Phone: (575) 628-4167		

* Attach Additional Sheets If Necessary

JMW1327034125

JMW1329440269

2RP-2011