

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

iJMW1329450065		<b>OPERATOR</b>		<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company OXY USA WTP LP 16696		Contact CAMPBELL, RODNEY			
Address 329 Marathon Rd, Lakewood		Telephone No. (578) 628-4167			
Facility Name INDIAN BASIN GAS PLANT		Facility Type GAS PROCESSING FACILITY			
Surface Owner		Mineral Owner INDIAN BASIN		Lease No.	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
		-	-					Eddy

Latitude 32\*27 52.502" Longitude 104\*34 28.004"

**NATURE OF RELEASE**

Type of Release Gas	Volume of Release 358 MCF	Volume Recovered 0
Source of Release Acid Gas Flare	Date and Hour of Occurrence 5/25/2013 5:28:00 PM	Date and Hour of Discovery 5/25/2013 5:28:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

RECEIVED

JUN 03 2013

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.\*

Cause:  
IBGP FLARED ACID GAS FOR 217 MINUTES DUE TO ACID GAS COMPRESSOR LUBRICATION LOW FLOW. PLANT ELECTRICIAN CAME OUT AND FOUND 3 BLOWN FUSES, DUE TO STATIC ELECTRICITY FROM SEVERE WEATHER STORM.

Remedial Action Taken:  
OPERATIONS TRIED TO START SEVERAL TIMES UNTIL OFF DUTY PLANT ELECTRICIAN ARRIVED TO FURTHER TROUBLESHOOT.

Describe Area Affected and Cleanup Action Taken.\*  
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: RODNEY CAMPBELL		Approved by District Supervisor: <b>Accepted for record NMOCD</b>	
Title: <i>HES Specialist</i>		Approval Date: <b>OCT 21 2013</b>	Expiration Date:
E-mail Address: RODNEY_CAMPBELL@OXY.COM		Conditions of Approval:	
Date: <i>5-28-13</i> Phone: 575-628-4167		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

iJMW1327034125

iJMW1329452043

2RP-2014