


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NJMW 1333652776 OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: Chevron 4323		Contact: Bradley Blevins	
Address: 1616 West Bender		Telephone No.: (575) 391-1462 Ext. 86424	
Facility Name: Skelly 952		Facility Type: Poly Line	
Surface Owner: BLM		Mineral Owner:	API: 30-015-32895

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	21	17S	31E					Eddy

Latitude: N 32° 49' 28.56" Longitude: W 103° 52' 44.04"

NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 53.8 bbls	Volume Recovered: 15 bbls
Source of Release: 3 rd party contractor doing road work damaged the main transfer water line	Date and Hour of Occurrence: 11/19/13 @ am	Date and Hour of Discovery: 11/19/13 @ am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Bradley Blevins	Date and Hour: 11/22/13 @ am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
Depth to Water: ~130 ft bgs		
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* Approximately 53.8 bbls of produced water were released when a 3 rd party contractor doing road work damaged the main water transfer line. Approximately 15 bbls volume recovered. The poly line has been repaired and an emergency response crew dispatched to remove surface contaminants.		
Describe Area Affected and Cleanup Action Taken.* An area approximately 725 ft x 10 ft was impacted by the release with ~15 bbls of fluid recovered from the site. Soil samples will be collected from release area and submitted to Cardinal Laboratories for testing. Upon receipt of laboratory analytical data from soil samples collected during delineation operations, a Remediation Proposal will be prepared for approval.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
OIL CONSERVATION DIVISION		
Signature:	Approved by District Supervisor: <i>Mike Bratcher</i>	
Printed Name: Bradley Blevins	Approval Date: DEC 02 2013	
Title: HE Specialist	Expiration Date:	
E-mail Address: bradley.blevins@chevron.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date:	Phone: (575) 391-1462 Ext. 86424	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
January 2nd, 2014 2RP-2087

Bratcher, Mike, EMNRD

From: Blevins, Bradley G <Bradley.Blevins@chevron.com>
Sent: Friday, November 22, 2013 9:24 AM
To: Bratcher, Mike, EMNRD; 'Amos, James'
Cc: Blevins, Bradley G
Subject: FW: FW: Spill skelly 952
Attachments: Skelly 952 Initial C-141.pdf

Please find the initial C-141 for the release that occurred on the Skelly 952. 3rd party struck one of our lines while repairing a road. If you have any questions please give me a call.

Thanks



Bradley Blevins
Chevron Delaware Basin
HE Specialist
Hobbs FMT
Direct 575-391-1462 86424
Cell- 575-441-0341

From: Daniel Dominguez [<mailto:ddominguezepi@gmail.com>]
Sent: Friday, November 22, 2013 9:08 AM
To: Blevins, Bradley G
Subject: Re: FW: Spill skelly 952

Bradley,

Revised Initial C-141 for Skelly 952 attached.

Sincerely,
ENVIRONMENTAL PLUS, INC.

Daniel Dominguez
Environmental Consultant/Safety Director

Environmental Plus, Inc.
P.O. Box 1558
2100 Avenue 'O'
Eunice, NM 88231
(575) 631-0401 (Cell)
(575) 394-3481 (Office)
(575) 394-2601 (fax)