District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santâ Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

DEC 0.6 2013

RECEIVED

Form C-141 Revised October 10, 2003

NMOCD ARTES District Office in accordance with Rule 116 on back side of form

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action											
NMEn	113344	142350	2			OPERA'	ГOR	✓ Initi	al Report		Final Report
Name of Co		Chevron De			5	Contact Bradley Blevins					
Address PO Box 190, Hobbs, NM 88241						Telephone No. (575) 391-1462					
Facility Na	me Little	efield Federa	al SWD #	1		Facility Type Well Location					
Surface Owner BLM : Mineral Owner								API#	API # 30-015-10259		
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the	North	n/South Line	Feet from the	East/West Line	e County		
В	11	248	31E	660		North	1980	East	Eddy County, NM		vI
Latitude <u>N 32.12729°</u> Longitude <u>W 103.74594°</u>											
NATURE OF RELEASE											
Type of Release Produced Water							Release 181 bb		Volume Recovered 170 bbls		
Source of Release Triplex pump failure							Hour of Occurrenc 3 @ 10:00 am				
Was Immedi	ate Notice (l Vac I	l No. D Not D	aavirad	If YES, To Whom?					
Yes No Not Required Mike Bratcher- NMOCD, James Amos- BLM											
By Whom? Bradley Blevins Was a Watercourse Reached?						Date and Hour 12/02/2013 @ 3:00 pm If YES, Volume Impacting the Watercourse.					
was a water	course Read		Yes 🗵	No	11 1 E.S., Volume impacting the watercourse.						
If a Watercourse was Impacted, Describe Fully.*											
							•				
Describe Cause of Problem and Remedial Action Taken.*											
A triplex pump failure caused 181 bbls of produced water to leak onto the ground. 170 bbls of fluid were recovered via vacuum truck and the pump was											
repaired.		ÿ ŗ					•				
Describe Are					anta di		0.1-1-1		t als	العالم	
A triplex pump failure caused 181 bbls of produced water to leak onto the ground. 170 bbls of fluid were recovered via vacuum truck and the pump was repaired. Further remediation will be performed in accordance with a remediation plan approved by NMOCD and the BLM.											
I hereby certi	ify that the i	information gi	ven above	is true and comp	lete to	the best of my	knowledge and u	nderstand that pur	suant to NM	OCD r	ules and
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger											
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state, or local laws and/or regulations.											
,	7		0 _	-		OIL CONSERVATION DIVISION					
Signature:	Shad	My St	Sing-			•		•	1.1		
Printed Name: Bradley Blevins						Approved by District Supervisor Signed By Mile Brance					
Title: HE Specialist						Approval D	IC 1 0 2013	Expiration	Date:		

* Attach Additional Sheets If Necessary

E-mail Address:

Date:

Bradley.blevins@chk.com

Phone: (575) 391-1462

Remediation per OCD Rule & Guidelines, & like approval by BLM. <u>SUBMIT REMEDIATION</u>

PROPOSAL NO LATER THAN:

Conditions of Approval:

2RP-2105

Attached [

Bratcher, Mike, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Friday, December 06, 2013 8:48 AM

To: Cc: Bratcher, Mike, EMNRD; jamos@blm.gov
'Bradley Blevins'; cbrunson@bbcinternational.com; kswinney@bbcinternational.com;

jgilkey@bbcinternational.com

Subject:

Initial C-141s, Littlefield Federal SWD #1 and Old Indian Draw CTB

Attachments:

Initial C-141, Littlefield Federal SWD #1.pdf; Initial C-141, Old Indian Draw CTB.pdf

Attached are the initial C-141s for leaks that occurred at the Littlefield Federal SWD #1 on 12/01/2013 and the Old Indian Draw CTB on 12/02/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240

Phone: (575) 397-6388 Fax: (575) 397-0397

Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From:

Blevins, Bradley G < Bradley. Blevins@chevron.com>

Sent:

Monday, December 02, 2013 2:52 PM

To:

Bratcher, Mike, EMNRD; 'Amos, James'

Cc: Subject: Blevins, Bradley G Release Littlefield SWD

Mike/Jim

Chevron had a release on the Littlefield SWD. Packing failed on triplex pump releasing 181 barrels of produced water to the location pad. 170 barrels of fluid was recovered with vacuum trucks. Cliff Brunson will follow up with initial C-141. If you need further info please let me know.

Thanks,



Bradley Blevins
Chevron Delaware Basin
HE Specialist
Hobbs FMT
Direct 575-391-1462 86424
Cell- 575-441-0341