HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. Firmer Dr., Spate Fe, NM 875

State of New Mexico Energy Minerals and Natural Resources

DEC 0 4 2013

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in RECENTATION ance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505												
			Rel	ease Notific	catio	n and Co	rrective A	ction				
						OPERA'	TOR	\boxtimes	Initia	al Report	Final Report	
							Contact Chancey Summers					
							Telephone No. (575) 397-8216					
							Facility Type Gathering					
Surface Ow	ner Jimi	my Weir		Mineral	Jwner		API NO. 30.025.26176 MEAREST WELL CE LAMUNYON!					
LOCATION OF RELEASE 048												
Unit Letter	Section	Township	Range	Feet from the	North	/South Line	Feet from the	East/West I	est Line County			
В	27	238	37E							Lea County, 1	NM I	
			J 3.2	T				Later		Lou county,		
Latitude Longitude												
NATURE OF RELEASE												
Type of Release Oil							Volume of Release			Volume Recovered		
Source of Release Fire tube on heater treater							Date and Hour of Occurrence			0 bbls Date and Hour of Discovery		
Source of the two of fields treated							11/20/2013				.,	
Was Immediate Notice Given?							If YES, To Whom?					
✓ Yes ☐ No ☐ Not Required							Geoffrey Leking-NMOCD; Jennifer Van Curen- BLM Date and Hour 11/20/13 @ 12:55 pm					
By Whom? Rachel McPherson Was a Watercourse Reached?												
was a watero	course Reac		Yes 🛭	No		11 1 E.S, V	If YES, Volume Impacting the Watercourse.					
If a Watercou	ree was Im	nacted Decor	ibe Fully	*		.L.,,						
If a Watercourse was Impacted, Describe Fully.*												
SUR L												
	DTW = 70' SURL											
Describe Cause of Problem and Remedial Action Taken.*												
Failure of a fi	re tube on t	the heater trea	ter caused	10 bbls of oil to	leak ont	o the ground.	No fluids were re	ecovered and	the fi	re tube was rep	aired/replaced.	
Describe Area	Affected a	and Cleanup A	Action Tak	cen:*								
		_										
The affected a NMOCD and		oximately 10'	x 150' in	side the berm. Re	emediati	ion will be co	mpleted in accord	ance with a r	emedi	ation plan appr	oved by	
INITOCD and	the BLIVI.											
I hereby certif	y that the i	nformation gi	ven above	is true and comp	lete to t	he best of my	knowledge;and u	nderstand tha	t purs	uant to NMOC	D rules and	
				nd/or file certain r								
				e of a C-141 repo								
				mivestigate and range of a C-141								
federal, state,				number of the 1771	roport a	oes not toner	e the operator of t	caponatomy	101 0	omphance with	any other	
				/			OIL CONS	SERVATI	ON	DIVISION		
Signature				\longrightarrow		South Res Leller						
Signature:				>>		Annuariad Fire						
Printed Name: Chancey Summers Approved by Environmental Specialist												
Title: HES Specialist A							e: 12/4/13	Expira	ation	Date: 2 4	14	
E-mail Address: Chancey.Summers@oxy.com C							Approval: SVB	MIT FIN	AL	Attached [

C-141 BY 2/4/14

(575) 397-8216

Phone:

IRP-2-14-3014

^{*} Attach Additional Sheets If Necessary