

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JAN 29 2014

Form C-141
Revised August 8, 2011

Submit only to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	Contact Bruce Baker
Address 8 Ellison Lane Eunice, NM 88231	Telephone No. (432) 631-6982
Facility Name WBDU # 12	Facility Type Oil Well

Surface Owner Millard Deck Estates	Mineral Owner	API No. 30-025-36340
------------------------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 9	Township 21S	Range 37E	Feet from the 1210'	North/South Line FNL	Feet from the 1470'	East/West Line FEL	County Lea
---------------	-----------	--------------	-----------	---------------------	----------------------	---------------------	--------------------	------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 3 barrels of oil and 5 barrels of water.	Volume Recovered 3 barrels of oil and 4 barrels of produced water
Source of Release Flow Line	Date and Hour of Occurrence	Date and Hour of Discovery 1-7-14 @ 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

DTW=69' JRG L 2/6/14

Describe Cause of Problem and Remedial Action Taken.*
Due to inclement weather the poly flow line ruptured on the well pad. The well was shut in and a vacuum truck was dispatched to recover fluid. The line was repaired.

Describe Area Affected and Cleanup Action Taken.*
A vacuum truck recovered 7 barrels of total fluid. The site was mapped and surface samples collected. On 1/10/2014 a vertical was excavated to 4 ft. below ground surface and samples collect and taken to a commercial laboratory for analysis for chloride and TPH. A corrective action plan will be submitted to NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION <i>Larry Baker</i> Approved by Environmental Specialist	
Printed Name: Bruce Baker	Environmental Specialist	
Title: Environmental Technician	Approval Date: 01/29/14	Expiration Date: 04/01/14
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval: SUBMIT FINAL C-141 BY 04/01/14	Attached <input type="checkbox"/> IRP-2-14-3016
Date: 1/29/14	Phone: (432) 631-6982	

* Attach Additional Sheets If Necessary

FEB 06 2014