District ! 1625 N. French Dr., Hobbs, NM 882 0

RECEIVED | state of New Mexico FEB 18 2 Minerals and Natural Resources

Form C-141 Revised August 8, 2011

District II 811 S. First St., Artesia, NM 88210

District III OOD Rio Brazos Road, Aztec, NM 8 140 OCD ARTES 1220 South St. Francis Dr.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 S. St. Francis Dr., Santa Fe, NM 87505

Santa Fe, NM 87505

Release Notification and Corrective Action												
nHMP	14071	41448	•			OPERA	ГOR	. Init	ial Report		Final Repor	
Name of Co	mpany De	von Energy	7	15025		Contact						
Address PO						Telephone No. 575- 748-3371						
Facility Nar	ne Apache	e 24-3 Batte	ry			Facility Type Oil						
Surface Owner Mineral Owner							API No. 30-015-28016					
LOCATION OF RELEASE												
Unit Letter A						South Line	Feet from the 405	East/West Line East	1			
Latitude: Longitude:												
NATURE OF RELEASE												
Type of Release Produced Water							Volume of Release 200 Volume Recovered 160 Date and Hour of Occurrence Date and Hour of Discovery					
Source of Release Punctured water transfer line							February 11, 2014; 1:30pm February 11, 2014; 4:00pm					
							If YES, To Whom?					
☐ Yes ☐ No ☐ Not Required							Jerry Mathews; Don Mayberry; Amancio Cruz Mike Bratcher-OCD/Jim Amos-BLM					
By Whom? Wes Ryan/Hub Perry						Date and Hour February 11, 2014; 4:15pm						
Was a Watercourse Reached? ☐ Yes ☒ No							lume Impacting th	he Watercourse.				
If a Watanaan								· · · · · · · · · · · · · · · · · · ·				
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.* At the Apache 24-3 battery a produced water transfer line was punctured when it was run over by a water truck causing it to spill down the road. Flow back drivers did not report the leak and the pumper had yet to make it to that section of his route for the day. A WIPP employee discovered the spill and contacted assistant foreman Wes Ryan who called the Lease Operator who then he went directly to the site and began to shut in the surrounding wells. When the lease operator realized that is was his transfer pump that was producing the leak he turned that off as well and immediately called for recovery trucks who started with cleanup and had roustabouts come out and repair flow line.												
Describe Area Affected and Cleanup Action Taken.* Spill flowed into a ditch approximately ¼ mile down the road. Roustabouts were called in to begin cleanup and recovery.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
Signature: Veronica Teel							OIL CONSERVATION DIVISION					
Signature. For Ornow 1000								1/		•		
Printed Name: Veronica Teel A							Approved by Environmental Specialist: Itualian					
Title: Field Admin Support A						Approval Date: 3/12/14 Expiration Date: NA						
E-mail Addres	s: Veronica	ı.Teel@dvn.c	om		C	Conditions of Approval: Attached						
Date: Februa Attach Additi				none: 575-748-99;	"	e approval b	per OCD Rule & by BLM. SUBMIT OSAL NO LATER	REMEDIATION-			2200	