District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 8, 2011

Release Notification and Corrective Action											
2RP-2199					<b>OPERATOR</b>			Initial	Report	$\boxtimes$	Final Report
Name of Company: BOPCO, LP					Contact: Tony Savoie						
Address: 522 W. Mermod, Suite 704, Carlsbad, NM 88220					Telephone No. (575)887-7329						
Facility Name: PLU-Pierce Canyon 17-24-30 USA #1H					Facility Type: Exploration & Production						
Surface Owner: Department of Interior BLM   Mineral Owner:					: BLM			API No. 30-015-40520			
LOCATION OF RELEASE											
Unit Letter Section	North	l l			/West Line County						
N 17		South 1,980			West Eddy						
Latitude 32.211095° North Longitude 103.905918° West											
NATURE OF RELEASE											
Type of Release Pr				Volume R	Recovered None						
Source of Release Unauthorized discharge from a transport truck					I I				Hour of Discovery		
Was Immediate Notice Given?					Unknown   2/14/14 at 10:30 a.m.   If YES, To Whom?						
∑ Yes											
By Whom? Tony Savoie					Date and Hour 2/14/14 at 11:04 a.m.						
Was a Watercourse Reached?  ☐ Yes ☑ No					If YES, Volume Impacting the Watercourse.  RECEIVED						
						APR <b>2 4</b> 2014					
									1 6 6 6 PM	4 -	
NMOCD ARTESIA											
Describe Cause of Problem and Remedial Action Taken.* The release was discovered during routine inspection of the well pad. The well has been shut in											
since 3/8/13											
Describe Area Affect											
activities, berms where installed to prevent the fluid from leaving the well pad onto the recently downsized area around the pad. The Pierce Canyon 17-24-											
30 USA #1H release site was remediated as per NMOCD and BLM recommended guidelines. Soil samples collected from the floor and sidewalls of the excavation were analyzed by an NMOCD-approved laboratory, which determined concentrations of BTEX, TPH and chloride were less than NMOCD											
regulatory standards in each of the submitted soil samples. Please reference the attached Remediation Summary and Site Closure Request for complete											
remediation details.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger											
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability											
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
rederal, state, or loca	laws and/or reg	ulations.				OIL CONG	TED V	ATION	DIVICI	ONI	
					OIL CONSERVATION DIVISION						
Signature:					1/		フ				
Printed Name: Tony		Approved by Environmental Specialist:									
			. 1.			El-lui			. 4	1	-
Title: Waste Manage	nent and Remed	liation Spec	ıalist		Approval Dat	e: 3/3/49		Expiration 1	Date: //	/+	
E-mail Address: tasa		Conditions of Approval:									
Date: 4/24/		Fixan									

<sup>\*</sup> Attach Additional Sheets If Necessary