State of New Mexico **Energy Minerals and Natural Resources**

HOBBS OCD

Form C-141 Revised August 8, 2011

IRP 06-14-3056

agrid.

617+ 1701485 4477 15

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

JUN Sabani20 Gopy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED **Release Notification and Corrective Action**

	OPERATOR	Initial Report	Final Report
Name of Company Devon Energy	Contact Kenny Kidd		
Address PO Box 250 Artesia, NM 88211	Telephone No. 575- 513-8545		
Facility Name Rio Blanco 4 Fed 3 SWD	Facility Type SWD		

Surface Owner Federal				Mineral Owner		API No. 30-025-36425		
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	4	235	34E	1650	SOUTH	1650	EAST	LEA

Latitude: ____ Longitude: ___

NATURE OF RELEASE								
Type of Release Produced Water	Volume of Release 65bbls	Volume Recovered 65bbls						
Source of Release Charge pump pipe	Date and Hour of Occurrence	Date and Hour of Discovery						
	5/30/14	5/30/14 11:30 AM						
Was Immediate Notice Given?	If YES, To Whom?							
Yes D No D Not Required		lichael-Assistant Foreman/ Scott Poe-						
		dent/Hobbs OCD-Geoffery Leking/BLM-						
	Jeff Robertson							
By Whom? Matt Nettles	Date and Hour 5/30/14 11:30 AM	· · · · · · · · · · · · · · · · · · ·						
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.							
🗋 Yes 🖾 No								
If a Watercourse was Impacted, Describe Fully.*	<u>,</u>							
	depth to gH20	> 100						
Describe Cause of Problem and Remedial Action Taken.*	Ũ							
The needle valve came out of the pipe which is connected to the char	a nume This agues of 65 hereals of	produced water to be released 60						
barrels in the containment and 5 bbls outside of the containment. The	e well was shut off A vacuum truck	was immediately called for vacuum						
services. 65 barrels of produced water was recovered. The pump wa		was mineutately cance for vacuum						
Services of burrels of produced when was recovered. The pump was repaired.								
Describe Area Affected and Cleanup Action Taken.*								
The area affected was within the burm approximately 30 feet wide b								
5 feet wide by 75 feet long. Talon LPE was contacted to perform the	site assessment and soil sampling a	ctivities.						
L bareby certify that the information given above is true and complete to	the best of my knowledge and underst	and that pursuant to NMOCD pulse and						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger								
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability								
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health								
or the environment. In addition, NMOCD acceptance of a C-141 report	loes not relieve the operator of respor	sibility for compliance with any other						
federal, state, or local laws and/or regulations.	· · · · · · · · · · · · · · · · · · ·							
	OIL CONSER	VATION DIVISION						
Signature: Shammy Ingram	nyny							
	Approved by Environmental Special	ist:						
Printed Name: Shammy Ingram								
Title: Field Admin Support	Approval Date: 6 - 3 - 14	Expiration Date: 7-29-14						

Conditions of Approval: Site Saples required Attached Deliaiste Brenediate site as per IRP 06-1 NMOCD prides - Subait Find 05 rid C-141 by 7-29# JUN \$ 2014 E-mail Address: Shammy.Ingram@dvn.com Date: May 30, 2014 Phone: 575-748-0174 * Attach Additional Sheets If Necessary