

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

JUN 02 2014

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Enterprise Field Services LLC	Contact: Jim Heap
Address: PO Box 4324, Houston, TX 77252	Telephone No.: 432-686-5404
Facility Name: Pipeline #1009	Facility Type: Pipeline

Surface Owner: Undetermined	Mineral Owner: Not Applicable (Pipeline)	API No.
-----------------------------	--	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	21S	34E	731	South	1247	East	Lea

Latitude: N 32.473687 Longitude: W -103.453333

NATURE OF RELEASE


Type of Release: <i>Natural Gas</i>	Volume of Release: <i>2.93 MMCF, 80 BBL Pipeline Liquids</i>	Volume Recovered: <i>35 BBL</i>
Source of Release: <i>Pipeline Leak</i>	Date and Hour of Occurrence: <i>02/16/2014 @ 18:00 MST (start)</i>	Date and Hour of Discovery: <i>02/16/2014 @ 20:00 MST (end)</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>OCD Region 1 (Bill Sonnamaker) by phone</i>	
By Whom? <i>Jim Heap</i>	Date and Hour: <i>02/17/2014 @ 08:00 MST</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
CAUSE: Push-weld failure; likely corrosion.
ACTION: The line was blown down at the weld. Line was repaired with a clamp.

Describe Area Affected and Cleanup Action Taken.*
All gas was lost to atmosphere.
Clean up action : Contaminated soil was removed and disposed. Confirmation samples were taken and showed the spill area had been excavated below the OCD RRAL's. NMOCD Region 1 (G. Leking) provided approval (5/12/2014) and the excavation was refilled with clean soil obtained from the landowner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jon E. Fields	Approved by Environmental Specialist: 	
Title: Director - Field Environmental	Approval Date: <i>7-2-14</i>	Expiration Date: _____
E-mail Address: jefields@eprod.com	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date: <i>5-29-2014</i> Phone: 713-381-6684		<i>6-14-3125</i>

* Attach Additional Sheets If Necessary

02/16 1000747
170 14 18359709

JUL 02 2014