

HOBBS OCD

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

JAN 17 2014

RECEIVED

State of New Mexico

Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-141
Revised August 8, 2011Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <u>Energen Resources Corporation</u>	Contact <u>Andy Cobb</u>
Address <u>3300 N. A St. Bldg 4, Ste 100, Midland</u>	Telephone No. <u>432 557 3145</u>
Facility Name <u>Lambirth State</u>	Facility Type <u>oil/gas Battery</u>

Surface Owner <u>State of Texas</u>	Mineral Owner <u>State of Texas</u>	API No. <u>3004120514</u>
-------------------------------------	-------------------------------------	---------------------------

SRL 5/01/14

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>H</u>	<u>36</u>	<u>05S</u>	<u>32E</u>	<u>1980</u>	<u>North</u>	<u>510</u>	<u>East</u>	<u>Roosevelt</u>

Latitude N 33.8461 Longitude W -103.6565

NATURE OF RELEASE

Type of Release <u>oil</u>	Volume of Release <u>631</u>	Volume Recovered <u>611</u>
Source of Release <u>oil tanks</u>	Date and Hour of Occurrence <u>1/13/14</u>	Date and Hour of Discovery <u>1/13/14 @ 8am</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>CCO</u>	
By Whom? <u>Callie Marsh</u>	Date and Hour <u>1pm 1/13/14</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <u>N/A</u>	

If a Watercourse was Impacted, Describe Fully.* N/ADescribe Cause of Problem and Remedial Action Taken.* Check on circulating pump was hung open, which lowered the pressure to the heater and causing fluid to go to skim tank instead of gas sales line and run the skim tank over.Describe Area Affected and Cleanup Action Taken.* The fluid remained in the firewall. Began remediation in place using biodegradable products.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Callie MarshPrinted Name: Callie MarshTitle: Safety & Environmental Coord.E-mail Address: callie.marsh@energen.comDate: 1/13/2014Phone: 432 686 3337

Approved by Environmental Specialist:

Approval Date: 2-7-14Expiration Date: 9-10-14

Conditions of Approval:

Site samples required
Religate & remediate
area as per NMOCD guides.Attached ☐7-14-3144

* Attach Additional Sheets If Necessary

Final C-141 due 9-10-14

0914 162928

1701418 850785

p 701418 851005

JUL 09 2014