

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

MAY 27 2014

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☐ Final Report

Name of Company CrownQuest Operating	Contact Brandon Willis
Address 500 W. Texas Ave, Suite 500 • P.O. Box 53310 • Midland, Texas 79710	Telephone No. 432-528-9830
Facility Name AN AT BG Battery	Facility Type Battery

Surface Owner	Mineral Owner	API No. 3002501141
---------------	---------------	--------------------

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	22	14S	33E					Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

## NATURE OF RELEASE

Type of Release Oil and Water	Volume of Release 230 bbls	Volume Recovered 116 oil/ 114 water
Source of Release oil and water tank	Date and Hour of Occurrence 5/24/2014 around 7:00 am	Date and Hour of Discovery 5/24/2014 around 7:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Brandon Willis	Date and Hour 5/27/2014 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Depth to G.H. 75-100'

Describe Cause of Problem and Remedial Action Taken.\*

Lighting struck oil tank around 7:00 am on 5/24/2014 at AN AT BG battery. Fumes were ignited and preceded to burn oil and gas from oil tanks and melted fiberglass water tank, poly line, and other equipment in the fire wall.



Remedial work to be done: broken and non-functioning equipment will be hauled to scrap yard. Soil will be tested and contaminated soil will be taken to Gandy-Marley facility. Facility will be rebuilt to previous specifications.

Describe Area Affected and Cleanup Action Taken.\*

oil and water from tanks spilled onto ground but contained in tank battery firewall. Approximately 230 bbls total fluid, 116 bbls of oil, 114 bbls of water were spilled and recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Brandon G. Willis	Approval Date: 7-8-14	Expiration Date: 9-11-14
Title: Lease Manager	Conditions of Approval: Site Specific required. Remediate & relocate site as per NMOCD guidelines. Submit final C-141 by 9-11-14	Attached <input type="checkbox"/>
E-mail Address: bwillis@crowquest.com		

JUL 09 2014

7-14-3149

09-14 213190

7701418 937492

0701418 937926

Date: 5/27/2014	Phone: 432-528-9830		
-----------------	---------------------	--	--

\* Attach Additional Sheets If Necessary