

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 7 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: David May
Address: 29 Vacuum Complex Lane	Telephone No. 575-391-3106
Facility Name: Philmex #9 SWD	Facility Type: SWD

Surface Owner: State	Mineral Owner: N/A	API No. 3002520516
-----------------------------	---------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter B	Section 26	Township 17S	Range 33E	Feet from the 660	North/South Line North	Feet from the 1980	East/West Line East	County LEA
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	----------------------

Latitude **32.8111601528043**Longitude **103.631763148299**

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 15 BBLs	Volume Recovered: 13 BBLs
Source of Release: 500 BBL tank	Date and Hour of Occurrence 10/11/13 9:45 pm	Date and Hour of Discovery SAME
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking	
By Whom? David May	Date and Hour: 10/14/13 10:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Spill was caused by a piece of rubber lodging inside of disposal pump causing it to lock down. MSO Shut in lease and other incoming fluids

Describe Area Affected and Cleanup Action Taken.*

Affected area was 31 feet X 61 feet and was contained inside the diked area. Spill will be remediated in place according to NMOCD requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: **David May**Title: **LEAD HSE**E-mail Address: **david.d.may@conocophillips.com**Date: **10/14/13**Phone: **575-391-3106**

Approved by Environmental Specialist:

Approval Date: **8-7-14**Expiration Date: **10-9-14**

Conditions of Approval:

*Site specific response
delimited remediate area
as per NMOCD guidelines*

Attached ☐**IRP-2996**

* Attach Additional Sheets If Necessary

*Submit final C-141 by
10-9-14*

*ogrid 217812**h to 1421946491**p to 1421946629*