<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS och State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011

Form C-141

P701421 957802

20 Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

·						OPERAT	OR	🛛 Ini	Initial Report			
Name of Company Devon Energy						Contact Ke						
Address PO Box 250 Artesia, NM 88211						Telephone No. 575- 513-8545						
Facility Name Rio Blanco 4 Fed Com 3 SWD						Facility Type SWD						
Surface Owner: Devon Mineral Owner						: Federal API No. 30-025-36425						
		<u>-</u>										
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range			South Line	Feet from the	East/West Line	1 -			
J	4	23S	34E	1650	S	OUTH	1650	EAST	LEA			
			La	titude: <u>32°19°5</u> 1	l.4"	Longitud	e: <u>-103°28°18.</u>	<u>7"_</u>				
NATURE OF RELEASE												
Type of Release: Valve on Y-strainer blew out						Volume of Release 20bbls Volume Recovered 15bbls						
Source of Release: Produced water						Date and H	3	Date and Hour of Discovery				
Was Immediate Notice Given?						·			8/05/14 3:37 PM			
was Immedia	te Notice C		Vac 🗆	No. Not Page	irad	If YES, To Whom? Kenny Kidd-Foreman/Ruben Garcia-Assistant Foreman/Matt Nettles-						
☐ Yes ☐ No ☐ Not Required						Assistant Foreman/Amancio Cruz-EHS/Roy White-Senior Production						
						Foreman/OCD-voicemail-Lesley/BLM-Jeff Robertson						
By Whom? Noel Espinosa - Banta						Date and Hour 8/05/14 3:37 PM						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
10 117												
If a Watercou	rse was Im	pacted, Descri	be Fully.*									
Describe Cause of Problem and Remedial Action Taken.*												
On August 5, 2014 at the Rio Blanco 4 Fed Com 3 SWD, a 1 inch valve on the bottom of a Y-strainer blew out resulting in approx. 20bbls of												
produced water to be released. Basic was called for vacuum services. Approximately 15 barrels of produced water were recovered.												
Describe Area Affected and Cleanup Action Taken.*												
	The area affected was 24 feet wide by 64 feet long and was contained within the impacted area of the old release. Talon LPE was contacted to											
perform the site assessment which will be addressed along with the previous release on 6/19/2014.												
							•				,	
				····								
				is true and complete								
				d/or file certain rele e of a C-141 report l								
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state,	or local lav	vs and/or regu	lations.				- 					
						OIL CONSERVATION DIVISION						
Signature: Shammy Ingram												
<i>J J</i>						Approved by Environmental Specialist:						
Chammy Ingram						. пристость г						
Printed Name: Shammy Ingram												
TOTAL - INSTALL A	J C	4				A D.4	. 9. 7	Famination	Data: ///	0- 11	,	
Title: Field A	amın Sup <u>ı</u>	ort				Approvai Dat	e: 8-7-14	Expiration	n Date: [0^	7-79		
E-mail Addre	ss: Shamm	y.Ingram@d	vn.com			Conditions of	Approval:		A 1	. —	}	
					\neg	9	ite Syphen ray	med	Attached	_		
Date: August 7, 2014 Phone: 575-748-0174						por NAOCD guide. 1RP-3218				8		
Attach Additional Sheets If Necessary Og-1d 6137												
Date: August 7, 2014 Phone: 575-748-0174 Attach Additional Sheets If Necessary AUG 0 8 2014 Attach C-141 by 10-9-14 Attached Attached												