

HOBBS OCD

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

AUG 18 2014

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name:	Corazon State Unit #8H	Facility Type:	Battery

Surface Owner: State	Mineral Owner: State	Lease No. (API#) 30-025-40950
----------------------	----------------------	-------------------------------

## LOCATION OF RELEASE

Unit Letter B	Section 10	Township 21S	Range 33E	Feet from the 100	North/South Line North	Feet from the 1980	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.5002828 Longitude -103.5581909

## NATURE OF RELEASE

Type of Release Oil	Volume of Release 30 bbls	Volume Recovered 28 bbls
Source of Release Gasket failure on heater treater	Date and Hour of Occurrence 8/9/2014 5:30 pm	Date and Hour of Discovery 8/9/2014 5:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? ---	
By Whom? Amanda Trujillo	Date and Hour 8/17/2014 8:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*



A gasket around the burner of the heater treater failed and caused the release. The issue was remediated by the replacement of the gasket and inspection of the fire tube.

Describe Area Affected and Cleanup Action Taken.\*

The impacted area was approximately 80' x 100' and in a lined facility. A vacuum truck was dispatched to recover all standing fluids and the facility was cleaned and returned to its previous condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 	
Printed Name: Amanda Trujillo	Approval Date: 8-19-14	Expiration Date: _____
Title: Senior Environmental Coordinator	Conditions of Approval: _____	
E-mail Address: atrujillo@concho.com	Attached <input type="checkbox"/>	
Date August 17, 2014 Phone: 575-748-6940	1RP-3248	

\* Attach Additional Sheets If Necessary

09-11-14 229137  
11-01-14 23 026423  
11-01-14 23 026614

AUG 18 2014