									HOBBS OCD				
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II				State of New Mexico Energy Minerals and Natural Res				Form C-141					
811 S. First St., District III						·			Submit 1 Copy to appropriate District Office in				
1000 Rio Brazos Road, Aztec, NM 87410						St. Franc		accordance with 19.15.29 NMAC.					
1220 C. Ch. Empire De. Courte De. MACOZEOE						Fe, NM 87505							
			Rele	ease Notific	cation	and Co	orrective A	ction					
		OPERATOR Initial Report X Final Report											
							enny Kidd						
Address PO Facility Nar			Telephone No. 575- 513-8545 Facility Type Oll										
Surface Owner Mineral Ow							1	05-14-3051					
LOCATION OF RELEASE													
Unit Letter Section Township Range Feet from the No						th/South Line Feet from the East/We			Vest Line				
A	A 23 17S 32E			335		North	260	EAST		LEA		a	
Latitude: <u>32.8263865'N</u> Longitude: <u>-103.7293355'W</u>													
NATURE OF RELEASE													
Type of Rele	ase Produc	Volume of Release 15bbis Volume Recovered 10bbis					lobbis						
Source of Release Jet pump malfunction						1	lour of Occurrenc	e		Hour of Discovery			
Was Immediate Notice Given?						5/22/14 10:00 am 5/22/14 10:00 am If YES, To Whom? 5/22/14 10:00 am							
		Garry Michael Assistant Foreman/Kenny Kidd-Foreman/Amancio Cruz- EHS/Jerry Mathews-SuperIntendent/OCD-Maxey Brown & Tomas Oberding/BLM-Jeff L. Robertson											
By Whom? Jeff Ables							Date and Hour 5/22/14 10:00 am						
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
If a Watercou	irse was Im	pacted, Descri	be Fully."	k		<u>I</u>						<u></u> , <u>8</u> ,8(-	
Describe Cau	Describe Cause of Problem and Remedial Action Taken.*												
OCD was no	One of the caps on one of the pistons on the jet pump backed off causing 15 barrels of produced water to spill on the ground. The BLM and the OCD was notified at 1:07 pm and 1:14 pm respectively. The size of the spill area was about 100 feet by 60 feet. Approximately 10bbls were												
recovered from the ground. Describe Area Affected and Cleanup Action Taken.* The impacted area in the vicinity of S-1, S-2, S-3, S-5, test pit location TP-1 and TP-2 was excavated to a depth of 1-foot deep. The impacted area in the vicinity of S-4 and TP-3 was excavated to a depth of 0.5-feet deep. The impacted area in the vicinity of 2-feet deep in accordance with NMOCD and BLM approved work plan. All the contaminated soil was transported to Lea Land, LLC. The excavated areas were then backfilled with new caliche, machine compacted and contoured to match the surrounding location. No further action is required.													
							knowledge and u						
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, states or lucal laws and/or regulations.													
Signature Undrad Larle							OIL CONSERVATION DIVISION						
Printed Name: SANORA DEARK							Approved by Environmental Specialist:						
Title: Field Admin Support							Approval Date: 8-28-19 Expiration Date:						
E-mail Addre	<u></u>	Conditions of Approval:				Attached							
Date: August 27, 2014 Phone: 575-746-5587										1	IRP - 3051		
* Attach Addi		ets If Necess					······						