

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

*nJMW 1400353566*

Name of Company <i>Enterprise Field Services LLC 1000347</i>		Contact <i>Jim Heap</i>	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
<i>PO Box 4324, Houston, TX 77252</i>		Telephone No. <i>432-686-5404</i>	
Facility Name <i>Pipeline ROW, Mercury Fee Line #2</i>		Facility Type: <i>Gas Gathering Pipeline</i>	
Surface Owner <i>Private-McDonald</i>	Mineral Owner <i>NA</i>	Lease No. <i>NA</i>	

LOCATION OF RELEASE


Unit Letter	Section <i>20</i>	Township <i>23S</i>	Range <i>28E</i>	Feet from the	North/South Line	Feet from the	East/West Line	County <i>Eddy</i>
-------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude *32.290685 N* Longitude *-104.117925 W*

NATURE OF RELEASE

Type of Release <i>Natural Gas and Pipeline Liquids</i>	Volume of Release <i>182 MCF, &lt;1 BBL of PPL liquids</i>	Volume Recovered <i>TBD</i>
Source of Release <i>Pipeline Leak</i>	Date and Hour of Occurrence <i>12/10/2013 18:00 (MST)</i>	Date and Hour of Discovery <i>12/10/2013 18:30 (MST)</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

*Suspected internal corrosion. The line was isolated, blown-down and scheduled for repair. Loss volume includes blow-down.*

Describe Area Affected and Cleanup Action Taken.\*

*Any impacted area will be determined when the line is excavated; landowner will be notified. Current observation shows a release of liquids to the surrounding area. Repair schedule is not known at the time of this report.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jon E. Fields</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Jon E. Fields</i>	Approved by District Supervisor: Signed By <i>Mike Brennan</i>	
Title: <i>Director, Field Environmental</i>	Approval Date: <i>JAN 03 2014</i>	Expiration Date:
E-mail Address: <i>jefields@eprod.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION</b>	Attached <input type="checkbox"/>
Date: Phone: <i>713-318-6684</i>	<b>PROPOSAL NO LATER THAN:</b> <i>Feb. 3 2014</i>	

\* Attach Additional Sheets If Necessary

*fJMW 1321052848*

*iJMW 1400354193*

*2RP-2137*




ENTERPRISE PRODUCTS PARTNERS L.P.  
ENTERPRISE PRODUCTS HOLDINGS LLC  
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

December 13, 2013

7012 2210 0001 2197 0902  
Return Receipt Requested

Mr. Mike Bratcher  
New Mexico Oil Conservation Division  
District 2 Office  
811 South First Street  
Artesia, New Mexico 88210



**RE: Form C-141 Report for Enterprise Products  
Gas Loss Reported in the Carlsbad Gathering Field**

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC please find enclosed the requisite C-141 Form for the December 12, 2013 release from our Mercury Fee gathering line in our Carlsbad Gathering Field, Eddy County. The leak is a suspected internal corrosion failure.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at [jkheap@eprod.com](mailto:jkheap@eprod.com) or me at 713-318-6595.

Regards,

Jon E. Fields  
Director, Field Environmental

/sjn  
attachments