District I					State of New Mexico								
1625 N. French	NM 88240				New Mexi and Natura		NOV 1	Fo rm C-14 1 August 8, 2011					
811 S. First St., Artesia, NM 88210 District III											-		
1000 Rio Brazos District IV	Road, Azte	c, NM 87410				ervation Division th St. Francis Dr. NMOCLI APraceordance with 19.15.29 NMAC.							
220 S. St. Francis Dr., Santa Fe, NM 87505Santa Fe, N							05						
Release Notification and Corrective Action													
NAB14	3235	3445	OPERATORInitial ReportFinal Report										
Name of Company Devon Energy ProductionLu137Address 6488 Seven Rivers Hwy Artesia, NM 88220						Contact Daniel Suniga- Devon Production Foreman Telephone No. 575-390-5850							
Facility Name Todd 26G Fed 2 SWD						Facility Type Salt Water Disposal							
Surface Owner Federal				Mineral (Ownei	Federal API No. 30-015-20277						1	
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the	North	h/South Line FNL	Feet from the 1650	East/West FEL					
0	G S26 T23S R31E		KJIE	1980		FNL	1050		·	Eddy	Eddy		
Latitude: 32.277191377827 Longitude: -103.745412550316													
NATURE OF RELEASE													
Type of Release Spill Oil						Volume of		Volume Recovered 40bbls oil					
Source of Release Oil tank overflow						Date and Hour of Occurrence November 09, 2014 ~8:30 AM			Date and Hour of Discovery November 09, 2014 9:00 AM				
Was Immediate Notice Given?						If YES, To Whom? d Mike Bratcher- OCD							
Yes No Not Required						Jeff Robertson- BLM							
By Whom? Wesley Ryan- Devon Assistant Production Foreman Was a Watercourse Reached?						Date and Hour November 10, 2014 11:21 AM; November 11, 2014 3:00 PM If YES, Volume Impacting the Watercourse							
Yes X No						N/A							
If a Waterco	urse was I	mpacted, Des	cribe Ful	ly.* N/A		1							
Describe Cause of Problem and Remedial Action Taken.* The DR-120-24V power supply that provides 24 VDC to the PLC failed and a loss of power occurred at the Todd 26G Fed 2 SWD that led to a spill of 45 bbls of oil. As a result of the power outage pumps and alarms lost power and communication with each other. The faulty unit was replaced and power was restored to the PLC.													
Describe Area Affected and Cleanup Action Taken.* A 60'x20' area of the pad at the Northwest side near the storage tanks inside the berm containment was affected by the spill requiring the aid of a vacuum truck provided by Standard Energy Services. 40 bbls of the 45 bbls of oil spilled were recovered. The contaminated caliche will be removed and replaced with clean caliche.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature: <i>Yuri Fernández</i>						OIL CONSERVATION DIVISION							
Printed Name: Yuri Fernandez						Approved by Environmenter Branch 11/4 Brancher							
Title: Field Admin Support						Approval Dat	te: 11/10/12	Exp	piration	Date:	IA		
E-mail Address: Yuri.Fernandez@dvn.com						Conditions of	f Approval:						
Date: November 11, 2014 Phone: 575.748.1846						Bemediation per O.C.D. Rules & Guidelines							
Attach Addi					I	ATER TH	1 4 5 1 6	1114		∎xµ s_#	100	2.1/11	
		•									LKP		

Bratcher, Mike, EMNRD

From:	Fernandez, Yuri <yuri.fernandez@dvn.com></yuri.fernandez@dvn.com>
Sent:	Wednesday, November 12, 2014 7:34 AM
То:	Bratcher, Mike, EMNRD
Subject:	Todd 26G Fed 2 SWD 45 bbls oil spill
Attachments:	Todd 26G Fed 2 SWD 45 bbls oil spill 11-09-2014.pdf; C-141 Todd 26 SWD 45 bbls oil
	spill 11-09-2014.doc

Good morning Mike,

Please see the attached files concerning the spill that occurred at the Todd 26G Fed 2 SWD of 45 bbls of oil. The pink dot and text are in reference to the approximate location of the spill.

Thank you,

Yuri Fernández

Field Admin Support Production

Devon Energy Corporation P.O. Box 250 Artesia, NM 88211 575 748 1846 <u>Yuri.Fernandez@dvn.com</u>

devon

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

