NM OIL CONSERVATION

Form C-141 NOV 2 4 7014 Revised August 8, 2011

RECEIVED Static Office in Received

ARTESIA DISTRICT

Submit 1 Copy to appropriate District Office in

State of New Mexico **Energy Minerals and Natural Resources**

> Oil Conservation Division 1220 South St. Francis Dr.

Santa Fe, NM 87505

District I

District II

District III

District IV

1625 N. French Dr., Hobbs, NM 88240

1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

811 S. First St., Artesia, NM 88210

Release Notification and Corrective Action OPERATOR Initial Report Final Report 246289 RKI E&P. LLC Zack Laird Contact 210 Park Ave. – Ste. 900, OKC, OK 73102 Telephone No. 405-742-2696 Facility Name: Santa Fe Federal 8 SWD Facility Type: SWD Surface Owner Federal Mineral Owner NA API No. 30-015-27126 LOCATION OF RELEASE Feet from the North/South Line East/West Line County Unit Letter Section Township Range Feet from the 35 **22S** 28E 760 FNL 460FEL Eddy Latitude: 32.3544216423605 Longitude: -104.05142600431 **NATURE OF RELEASE** Type of Release. Produced Water Volume of Release 1225 Bbls Volume Recovered 1170 Bbls Source of Release Injection line swedge Date and Hour of Occurrence Date and Hour of Discovery 11/22/14 – prior to 1000hrs MT 11/22/14 - 1000hrs MT If YES, To Whom? Was Immediate Notice Given? Heather Patterson - NM OCD (Voicemail) Sol Hughes - BLM (Discussed Spill) By Whom? Zack Laird - Sr. EHS Manager Date and Hour 11/24/14 - 1130hrs (CT) Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* The injection line running from the triplex pump to the wellhead developed a leak at a swedge that connects a 90 degree elbow to the 2 7/8" flow line. The threads in the swedge connection broke and allowed the leak to occur, vibration is thought to be the cause of the swedge failure. The injection line is thought to be the original from 1999, RKI rebuilt nearly all surface facilities upon acquiring this SWD in 2008, but the injection line was not replaced or rebuilt. Upon discovery of the spill, the triplex pump was shut down and water tanks were diverted to a different disposal. Four (4) vac trucks were dispatched to recover free fluids. Allowing location to dry out now, will delineate potential salt contamination and determine remedial plan. Describe Area Affected and Cleanup Action Taken.* All fluid remained on SWD pad (berm was in place around pad), 1170/1225 Bbls spilled were recovered. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by Environmental Specialist: Printed Name: Zack Laird **Expiration Date:** Title: Sr. EHS Manager Approval Date: [[E-mail Address: ZLaird@rkixp.com Conditions of Approval: Attached Remediation per O.C.D. Rules & Guidelines Date: 11/24/14 Phone: 405-987-2213 Submit remediation proposal no Attach Additional Sheets If Necessary

LATER THAN:

Patterson, Heather, EMNRD

From:

Zackary Laird <ZLaird@rkixp.com>

Sent:

Monday, November 24, 2014 10:01 AM

To:

Patterson, Heather, EMNRD; Hughes, Solomon Gene Thompson; Brandon Ripley; Kipper Folmar

Cc: Subject:

RKI Spill Notification and C-141

Attachments:

NM_SantaFeFed8SWD_InitialC141(112414).pdf

Heather/Sol,

Attached, please find completed OCD form C-141 for a spill occurring at the RKI Santa Fe Federal 008 SWD well in Eddy County, NM (API # 30-015-27126). Heather, I did try to reach you via phone and left a voicemail. I was able to reach Sol via phone, and we discussed the spill.

Please feel free to contact myself or a local RKI representative with any questions.

Regards,

Zack Laird | Sr. EHS Manager

RKI Exploration & Production, LLC

210 Park Avenue, Suite 900 | Oklahoma City, OK 73102 405.987.2213 (o) | 405.742.2696 (m) | ZLaird@rkixp.com

This email is confidential. If you believe it has been sent to you in error, then do not read it, do notify the sender you have received it, and delete it. Email transmissions cannot be warranted to be secure or error-free as information could be intercepted, misdirected, corrupted, lost, incomplete, destroyed or containing viruses. The sender therefore cannot guarantee the integrity or security of this email or any file(s) included herewith. RKI and the sender hereby disclaim any and all liability for injury or damages that may result from the recipient(s) receipt or transmission of this email and any file(s) included herewith or reliance on the contents thereof. Any oilfield equipment, materials or services ordered by or provided to RKI or its affiliates in connection with this message shall be governed by RKI's Terms and Conditions of Purchase (a copy of which may be found at www.rkixp.com) and such Terms and Conditions of Purchase are hereby incorporated and expressly made a part hereof. A paper copy of RKI's Terms and Conditions of Purchase will be provided upon your written request.

ENVIRONMENTAL RELEASE NOTIFICATION

Call-In Sheet Notice received by: _____ Type of Release

| Column | Co Briefly Describe Cause of Problem and action taken: Bern on Pal *405-742-2696 * Zack Rain RKI 9:27 am 11/24/14

Notice given by: Name/ Company

Date/Hour Immediate Notice given Date C-141 received: 11/24/14 2RP- 21235 FLARE NOTIFICATION Call-In Sheet Notice received by: _____ Date: _____ Name of Company/Phone # **Facility Name** Date of Occurrence Date/Hour of Flare Type of Release Flared MCF Volume Volume Recovered Briefly Describe Cause of Problem and action taken: Notice given by: Name/Company Date/Hour Immediate Notice given

Date C-141 received:

2RP-____