

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JAN 19 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

NAB1502956282

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Oxy USA	Contact Tiffney Burkham
Address 1502 W Commerce	Telephone No. 575-706-3616
Facility Name Pure Gold D-1 Battery	Facility Type

Surface Owner	Mineral Owner	API No: 3001527347
---------------	---------------	--------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	28	23S	31E	330	S	2310	E	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release GAS	Volume of Release 630MCF	Volume Recovered 0
Source of Release	Date and Hour of Occurrence 1/5/2015	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Tiffney Burkham	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

High gas line pressure caused by Enterprise Sand dune Compressor being shutdown.

Describe Area Affected and Cleanup Action Taken.\*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tiffney Burkham</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tiffney Burkham	Signed By <u>Mike Bratcher</u> Approved by Environmental Specialist:	
Title: HES Administrative Assistant	Approval Date: <u>1/25/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: Tiffney_burkham@oxy.com	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: 1/19/2014 Phone: 575-628-4116		

\* Attach Additional Sheets If Necessary

2RP-2771

## Bratcher, Mike, EMNRD

---

**From:** Tiffney\_Burkham@oxy.com  
**Sent:** Monday, January 19, 2015 7:59 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Benjamin\_Watkins@oxy.com  
**Subject:** C141's Pure Gold D-1 Pure Gold B-4 & Federal 29-8 Mobil Federal Battery  
**Attachments:** Document.pdf

Mr. Bratcher,,

I have attached the C141's for these locations. Please let me know if you have any questions. Hope you have a great day!

Tiffney Burkham  
HES Administrative Assistant  
Permian Resources  
(O) 575-628-4116  
(C) 575-706-4374  
[tiffney\\_burkham@oxy.com](mailto:tiffney_burkham@oxy.com)

-----Original Message-----

**From:** Burkham, Tiffney M  
**Sent:** Monday, January 05, 2015 11:40 AM  
**To:** 'Bratcher, Mike, EMNRD'  
**Cc:** Watkins, Benjamin I; Tramell, Austin W  
**Subject:** C129 Pure Gold D-1 Pure Gold B-4 & Federal 29-8  
**Importance:** Low

Mr. Bratcher,

This is to inform you that Oxy is flaring at the Federal 29-8, Pure Gold D-1 Battery & Pure Gold B-4. This is due to High gas line pressure caused by Enterprise Sand Dune Compressor being down. I have attached the C129's and will send out the C141 once we have stopped flaring. Let me know if you have any questions.

Tiffney Burkham  
HES Administrative Assistant  
Permian Resources  
(O) 575-628-4116  
(C) 575-706-4374  
[tiffney\\_burkham@oxy.com](mailto:tiffney_burkham@oxy.com)