NM OIL CONSERVATION

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

2RP-21760

JAN 28 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

100 April 150335269 OPERATOR Initial Report Final Report													
11/1015	0335	2/044	,			OPERA	ГOR			al Report	\boxtimes	Final Report	
Name of Co	mpany: C	OG Operati	22413	2/	Contact: Robert McNeill								
Address: 60	0 West Illi	inois Avenue	d TX 79701		Telephone No. 432-230-0077								
Facility Nar	ne: Parlian	nent 1 Feder	JBB #4H		Facility Type: Battery								
				1.0001.0001.0001									
Surface Ow	ner: Feder	al	Mineral O	wner:	: API No. 30-015-42647					l			
				LOCA	TIO	N OF REI	LEASE						
Unit Letter				North	n/South Line	Feet from the	East/West Line		County				
Н	<u> </u>	17S	29E	2310		North	150		East	Eddy		<u>y</u>	
			Lat	itude32.8646035	2764	54 Longitud	e -104.02015743	34034					
NATURE OF RELEASE													
Type of Release:							Volume of Release: Volume Recovered						
Produced Water Source of Release:							250 bbls 245 bbls Date and Hour of Occurrence: Date and Ho				laur af Disasyary		
Over ran tank		Date and Hour of Occurrence: 1/6/2015 6:30 am Date and Hour of Discovery 1/6/2015 6:30 am					covery	•					
Was Immedia		Given?				YES, To Whom?							
Yes No Not Required													
By Whom?	By Whom? Date and Hour:												
Was a Water	course Read	ched?	······································			If YES, Volume Impacting the Watercourse.							
☐ Yes ☒ No													
If a Watercourse was Impacted, Describe Fully.* 1112 T 2112 1 114-1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2													
If a Watercourse was Impacted, Describe Fully.* NO Immedia te Notifica tom													
·													
Describe Cause of Problem and Remedial Action Taken.* High volume alarms failed due to 3 rd party. Vacuum trucks and a high pressure washer were dispatched to pick up standing fluid and clean location.													
riigh volume alarms raned due to 3 party. Vacuum trucks and a high pressure washer were dispatched to pick up standing fluid and clean location.													
Describe Are	ea Affected	and Cleanup	Action I a	ken. *									
This release	occurred wi	ithin a lined fa	cility. No	additional action i	is reau	ired on this lo	cation.						
				e is true and compl									
				nd/or file certain rece of a C-141 repo									
				y investigate and re									
or the enviro	nment. In a	addition, NMC	OCD acce	ptance of a C-141	report	does not reliev	e the operator of	respons	ibility for o	compliance v	with an	y other	
		ws and/or reg			•								
		,		~** ~1			OIL CON	SERV	/ATION	DIVISION	<u>NC</u>		
		6	i,ie	Cla .		$^{\prime}$							
Signature:						Assessed the Freedom and Constitute //							
Printed Nam	e: Amanda	Truiillo				Approved by Environmental Specialist:							
Triniod Fideli	o. minanaa	Trajino					21011				7几		
Title: Senior	Environme	ntal Coordina	tor			Approval Da	te: 0 0 1 10		Expiration	Date: N	7		
				*		1.1				1			
E-mail Address: atrujillo@concho.com							Conditions of Approval;						
- INAL													
* Attach Add				: 575-748-6940			; 1 °						
Anach Add	monai one	ets ii ineces:	sai y								^	~~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	

Patterson, Heather, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Wednesday, January 28, 2015 6:14 PM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; james_amos@blm.gov

Subject: (Notification/C-141 Initial-Final) Parliament 1 Federal Com UBB #4H (30-015-42647)

Attachments: 1-6-2015 Parliament 1 Federal Com UBB #4H (TB) Initial Final.pdf

Mr. Bratcher/Mr. Amos,

COG Operating LLC is reporting a release on the Parliament 1 Federal Com UBB #4H (30-015-42647)

Unit H Section 1, Township 17S Range 29E The release occurred at 6:30 am on 1/6/2015

Released: 250 bbls PW Recovered: 245 bbls PW

The release was caused by high volume alarms failing due to 3rd party error. The release occurred within a lined facility. All fluids were able to be recovered. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator COG Operating LLC Cell: 505.350.1336 Office: 575.748.6930 atrujillo@concho.com

2208 W. Main St. Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.