NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

JAN **0 8** 2015

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
RECEIVED District Office in accordance
with Rule 116 on back
side of form

FAB 1503 626407 Release Notification and Corrective Action													
NAB 15						OPERAT	OR			al Report	☐ I	Final Report	
Name of Company: Duke Energy Field Services 180055 Contact: Nicholas L. Case													
			0 W. , ///	laland, 7X		Telephone No. (575)667-5225 (575)802-5225 Facility Type: Compressor Station							
Surface Ow	ner			Mineral O	wner	Lease No.							
				_LOCA	TION	OF REI	LEASE						
Unit Letter	Section	Township	Range	Feet from the	North/S	/South Line Feet from the East/West		Vest Line	County				
Latitude 32. 10'16.098" N_ Longitude 140. 14'30.887" W _ 32. 17!138													
Type of Release water/ condensate mix							ne of Release 20BBls Volume Recovered						
Source of Release transport truck							Date and Hour of Occurrence Date and Hour of Discovery						
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required							If YES, To Whom? Randy Dade by telephone message (575-626-1372) (also will E-mail this form upon completion)						
By Whom? Nicholas L. Case							Date and Hour 01/04/2015 at 09:50						
Was a Watercourse Reached? ☐ Yes ☒ No							If YES, Volume Impacting the Watercourse.						
If a Watercou	ırse was Im	pacted, Descr	ibe Fully.	*									
Describe Cause of Problem and Remedial Action Taken.* Transport truck was getting ready to load out slop tanks and found a malfunctioned/ failed "hose" that spilled a condensate/ produced water mix of approx. 20 BBl's into the truck load out containment. The driver replaced the hose and sucked up as much of the mostly water mix that he could (all but about 5 gallons).													
Describe Area Affected and Cleanup Action Taken.* The affected area was the Black River CS truck load out earthen berm. The driver sucked out the free standing liquid from the spill.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
						OIL CONSERVATION DIVISION							
Signature: Printed Name: Nicholas L. Case							Approved by District Supervisor: Signed By Mile Brances						
Title: Enviro						Approval Da	1e: 2/4/15		Expiration	Date: N	HA		
E-mail Address: NLCase@dcpmidstream.com Conditions of Approval: Remediation per O.C.D. Rules & Guidelines arched													
Date: 01	/04/2015			Phone: (575)802-5	225 Ple	mediation	n per U.C.D. h	ruies Dropa	or Guide OSAL N	C			

LATER THAN:_

Bratcher, Mike, EMNRD

From:

Dade, Randy, EMNRD

Sent:

Thursday, January 08, 2015 3:03 PM

To:

Bratcher, Mike, EMNRD

Subject:

FW: Initial C-141 for the spill at Black River CS on 01/04/2015

Attachments:

c141 initial 01042015 black river.pdf

From: Case, Nicholas L [mailto:NLCase@dcpmidstream.com]

Sent: Sunday, January 04, 2015 10:55 AM

To: Dade, Randy, EMNRD

Cc: Bebbington, Jon D; Mendenhall, Quentin; Cook, John W; Nesbit, Heath; Blair, Yvonne B; Owens, Mark R; Bonner,

Roberta L; Landenberger, Dan R

Subject: Initial C-141 for the spill at Black River CS on 01/04/2015

Randy: here is the Initial C-141 for the spill at Black River CS on 01/04/2015

I tried to reach you at 10:10 by phone but reached your answering machine in which I left you a detailed message.

The driver did a great job in immediately recovering almost all the fluids from the earthen containment.

Once the roads clear up I will make a visit to the site.

Thanks

Nicholas L. Case Environmental Specialist

DCP Midstream, LP 10 Desta Drive, Suite 400 West Midland, TX 79705 Ofc: 575-677-5225 Cell: 575-802-5225

e-mail: NLCase@dcpmidstream.com

