

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

FEB 12 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1504835072

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	RKI E&P, LLC	Contact	Zack Laird
Address	210 Park Ave. - Ste. 900, OKC, OK 73102	Telephone No.	405-742-2696
Facility Name:	North Brushy Draw 35-4H	Facility Type :	Oil and Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42290
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	25S	29E		175 FSL		2365FWL	Eddy

Latitude: 32.0793265 Longitude: -103.9554992

NATURE OF RELEASE

Type of Release. Oil	Volume of Release: 30Bbbls	Volume Recovered: 30Bbbls
Source of Release Tanks over ran because oil wasn't hauled	Date and Hour of Occurrence 02/12/15 - 0800hrs MT	Date and Hour of Discovery 02/12/15 - 0900hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson (left VM on office line)	
By Whom? Zack Laird	Date and Hour: 02/12/15 - 1530hrs CT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*



Oil tanks ran over during normal well production activity because oil wasn't hauled.

Dispatched oil haulers to haul oil. Recovered oil from lined containment with vacuum truck and wash containment.

Describe Area Affected and Cleanup Action Taken.*

All fluid remained in secondary containment berm, 30/30Bbbls recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zack Laird	Approved by Environmental Specialist: 	
Title: Sr. EHS Manager	Approval Date: 2/17/15	Expiration Date: N/A
E-mail Address: ZLaird@rkixp.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 02/12/15 Phone: 405-987-2213	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 3/17/15	

* Attach Additional Sheets If Necessary

2RP-2814

Patterson, Heather, EMNRD

From: Taylor Jones <TJones@rkixp.com>
Sent: Thursday, February 12, 2015 2:49 PM
To: 'Heather.Patterson@state.nm.us'
Cc: shughes@blm.gov; Zackary Laird
Subject: RKI E&P Spill Notification and C-141
Attachments: NM_Ross Draw14_InitialC141(021215)-signed.pdf; NM_RDX17-14_InitialC141(021215).pdf; NM_NBD35-4H_InitialC141(021215).pdf

Heather,

Attached please find completed OCD forms C-141 for spills occurring at three RKI wells: Ross Draw #14, RDX 17-14, and North Bushy Draw 35-4H in Eddy County. Zack Left you a voicemail regarding the spills on the RDX 17-14 and North Bushy Draw 35-4H.

Please feel free to contact myself or a local RKI representative with any questions.

Thank you,

Taylor Jones
RKI Exploration & Production, LLC
210 Park Avenue, Suite 900
Oklahoma City, OK 73102
405-996-5782 (o) | 405.326.0791 (m)
TJones@RKIXP.com

This email is confidential. If you believe it has been sent to you in error, then do not read it, do notify the sender you have received it, and delete it. Email transmissions cannot be warranted to be secure or error-free as information could be intercepted, misdirected, corrupted, lost, incomplete, destroyed or containing viruses. The sender therefore cannot guarantee the integrity or security of this email or any file(s) included herewith. RKI and the sender hereby disclaim any and all liability for injury or damages that may result from the recipient(s) receipt or transmission of this email and any file(s) included herewith or reliance on the contents thereof. Any oilfield equipment, materials or services ordered by or provided to RKI or its affiliates in connection with this message shall be governed by RKI's Terms and Conditions of Purchase (a copy of which may be found at www.rkixp.com) and such Terms and Conditions of Purchase are hereby incorporated and expressly made a part hereof. A paper copy of RKI's Terms and Conditions of Purchase will be provided upon your written request.