

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

FEB 26 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1506157520

0137 OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production Company, LP	Contact	Production Foreman; Joah Weidemann
Address	PO Box 250 Artesia, NM 88211	Telephone No.	575-513-1528
Facility Name	Laguna Salado South I	Facility Type	Oil Well

Surface Owner:	Federal	Mineral Owner:	Federal	API No	30-015-26407
----------------	---------	----------------	---------	--------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	22	23S	29E	2030	North	1980	West	Eddy

Latitude: 32.2922560548116

Longitude: -103.974771533511

NATURE OF RELEASE

Type of Release	Oil Spill	Volume of Release	8BBLS	Volume Recovered	8BBLS
Source of Release	vent tank overflow	Date and Hour of Occurrence	January 22, 2015 9:45 AM	Date and Hour of Discovery	January 22, 2015 9:45 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required				
If YES, To Whom?	Jeff Robertson; BLM & Mike Bratcher; OCD				
By Whom?	David Washington; Assistant Production Foreman				
Date and Hour	January 22, 2015 2:00 PM				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If YES, Volume Impacting the Watercourse	N/A				

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
The 2" valve leading from the 1440# separator to the water tanks was closed causing the vent tank to run over. The valve was immediately open upon discovery of the release to prevent further release.

Describe Area Affected and Cleanup Action Taken.*
6 of the 8 released BBLS of oil were contained within the lined secondary containment. 2 of the 8 BBLS of released oil overflowed from the secondary containment onto the well pad on the north side of the vent tank. The size of the affected area was approximately 15'x15'. A vacuum truck recovered all 8 BBLS of oil spilled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandy Farley</i>	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	Signed By <i>Mike Bratcher</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: sandy.farley@devon.com	Approval Date: 3/2/15	Expiration Date: N/A
Date: 01-23-2014 Phone: 575.746.5587	Conditions of Approval:	
	in accordance with O.C.D. Rules & Guidelines	
	ATTACHED REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

APPROVED BY: 4/2/15

2RP-2845

Bratcher, Mike, EMNRD

From: Harris, Jacqui <Jacqui.Harris@dvn.com>
Sent: Thursday, February 26, 2015 3:03 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Singleton, Stacie
Subject: Laguna Salado South 1 Initial C-141
Attachments: Laguna Salado South 1 Spill 8BBLS 1.22.15 Initial C-141.pdf; Laguna Salado South 1 Spill 8BBLS 1.22.15 GIS Image.pdf; Laguna Salado South 1 Spill 8BBLS 1.22.15 pic 4 of 6.JPG; Laguna Salado South 1 Spill 8BBLS 1.22.15 pic 1 of 6.JPG; Laguna Salado South 1 Spill 8BBLS 1.22.15 pic 6 of 6.JPG; Laguna Salado South 1 Spill 8BBLS 1.22.15 pic 2 of 6.JPG; Laguna Salado South 1 Spill 8BBLS 1.22.15 pic 3 of 6.JPG; Laguna Salado South 1 Spill 8BBLS 1.22.15 pic 5 of 6.JPG

Mr. Bratcher,

Please find the attached C-141, GIS image, & pictures of the spill for the Laguna Salado South 1. This C-141 was sent inadvertently to the BLM only on 1-26-15. We deeply apologize for this oversight and will make sure that it does not happen again.

Thank you,

Jacqui Harris

Field Admin Support
A-Schedule
Devon Energy Corporation
PO Box 250
Artesia, New Mexico 88211
575-748-0191



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.