

## Bratcher, Mike, EMNRD

---

**From:** Lupe Carrasco <LCarrasco@yatespetroleum.com>  
**Sent:** Tuesday, July 02, 2013 11:46 AM  
**To:** 'mburton@blm.gov'; Bob Asher; Katie Parker; Amanda Trujillo  
**Cc:** Bratcher, Mike, EMNRD; 'jamos@blm.gov'  
**Subject:** Re: Mimosa SWD #1

The crew was going to take care of that area as well. I'm out this week, but if it is not done when I get back I will have it taken care of then. I'll let you know.

Thanks!

Lupe

---

**From:** Burton, Michael <mburton@blm.gov>  
**To:** Lupe Carrasco  
**Cc:** Mike Bratcher <mike.bratcher@state.nm.us>; James Amos <jamos@blm.gov>  
**Sent:** Tue Jul 02 10:59:07 2013  
**Subject:** Re: Mimosa SWD #1

Lupe,

On 06/28/2013 I stopped by the Mimosa SWD spill. There was a back hoe working in the S1 area. My concern is the S2 area. The sidewalls are not clean. You can see this in the pictures that are attached. I realize the safety issues with digging around the tanks but the outer sidewalls still need to be removed.

Thanks

**Mike Burton**  
**BLM-CFO**  
**Environmental Protection Specialist**  
**575-234-2226 office**  
**575-361-3574 cell**  
**mburton@blm.gov**

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

On Fri, Jun 28, 2013 at 10:33 AM, Lupe Carrasco <LCarrasco@yatespetroleum.com> wrote:

Mike Bratcher,

As per our phone conversation on June 27, 2013, we have begun backfill of the S1 sample area at Mimosa SWD #1. Due to safety concerns of the excavation and the lack of space to properly bench the excavation, my

contractors are in the process of backfilling with fresh caliche. The S1 area has been excavated down to 8' at which point a solid bedrock layer prevented any further excavation. All soil removed will be disposed at an NMOCD approved disposal site. Please feel free to contact me with any questions or concerns.

Thanks!

Lupe Carrasco

*Environmental Regulatory Agent*

Yates Petroleum Corporation

Office: (575) 748-4350

Fax: (575) 748-4131

Cell: (575) 513-9074

---

**This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.**

---

---

**This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.**

---

</font

**Bratcher, Mike, EMNRD**

---

**From:** Burton, Michael <mburton@blm.gov>  
**Sent:** Tuesday, July 02, 2013 10:59 AM  
**To:** Lupe Carrasco  
**Cc:** Bratcher, Mike, EMNRD; James Amos  
**Subject:** Re: Mimosa SWD #1  
**Attachments:** P6280264.JPG; P6280266.JPG; P6280263.JPG

Lupe,  
On 06/28/2013 I stopped by the Mimosa SWD spill. There was a back hoe working in the S1 area. My concern is the S2 area. The sidewalls are not clean. You can see this in the pictures that are attached. I realize the safety issues with digging around the tanks but the outer sidewalls still need to be removed.  
Thanks

**Mike Burton**  
**BLM-CFO**  
**Environmental Protection Specialist**  
**575-234-2226 office**  
**575-361-3574 cell**  
**[mburton@blm.gov](mailto:mburton@blm.gov)**

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

On Fri, Jun 28, 2013 at 10:33 AM, Lupe Carrasco <[LCarrasco@yatespetroleum.com](mailto:LCarrasco@yatespetroleum.com)> wrote:

Mike Bratcher,

As per our phone conversation on June 27, 2013, we have begun backfill of the S1 sample area at Mimosa SWD #1. Due to safety concerns of the excavation and the lack of space to properly bench the excavation, my contractors are in the process of backfilling with fresh caliche. The S1 area has been excavated down to 8' at which point a solid bedrock layer prevented any further excavation. All soil removed will be disposed at an NMOCD approved disposal site. Please feel free to contact me with any questions or concerns.

Thanks!

Lupe Carrasco

*Environmental Regulatory Agent*

Yates Petroleum Corporation

Office: (575) 748-4350

Fax: (575) 748-4131

Cell: (575) 513-9074

---

**This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.**

---

YATES PET MILLMOSE SWD #1






Photo by Mike Kurten w/BLM

Photo by Mike Watson w. BL



Yates Pet MIMUSA SWA#1

PET MINUSA SW.

