

## Bratcher, Mike, EMNRD

---

**From:** Gregston, Terry G [tgregsto@blm.gov]  
**Sent:** Tuesday, October 11, 2011 3:30 PM  
**To:** dfrick@linenergy.com; RRagland@linenergy.com; JHernandez@linenergy.com;  
fred@etechnv.com; Bratcher, Mike, EMNRD  
**Subject:** RE: Turner B 113 spill: renamed Turner B 111 30-015-29530 2RP-932  
**Categories:** Yellow Category

Gentlemen,

The following information and spill map was sent out and attributed to the Turner B 113 well, which was the closest well to the spill. Linn Operating is currently calling the spill by a different name, which is creating a lot of confusion. So I have changed the spill name in all the federal databases, case files, and emails to the Turner B 111 spill. The forwarded spill map is still applicable...just change the spill name on the map to the Turner B 111.

Thank you,

### **Terry Gregston**

Environmental Protection Specialist  
Bureau of Land Management  
620 E. Greene St.  
Carlsbad, NM 88220  
Office (575) 234-5958  
Cell (575) 361-2635  
Fax (575) 234-5927

**Confidentiality Warning:** This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

---

**From:** Gregston, Terry G  
**Sent:** Wednesday, October 05, 2011 1:01 PM  
**To:** 'dfrick@linenergy.com'; 'RRagland@linenergy.com'; 'JHernandez@linenergy.com'; 'fred@etechnv.com'; 'mike.bratcher@state.nm.us'  
**Subject:** Turner B 113 spill: arch requirements, spill map

Gentlemen,

The spill that recently occurred just north of the Turner B 113 will require an arch survey, and pending upon the results of the arch survey, may require a monitor.

The spill map is attached.

Thank you for your attention to this concern,

### **Terry Gregston**

Environmental Protection Specialist

Bureau of Land Management  
620 E. Greene St.  
Carlsbad, NM 88220  
Office (575) 234-5958  
Cell (575) 361-2635  
Fax (575) 234-5927

**Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.**

## **Bratcher, Mike, EMNRD**

---

**From:** Gregston, Terry G [tgregsto@blm.gov]  
**Sent:** Wednesday, October 05, 2011 1:01 PM  
**To:** dfrick@linenergy.com; RRagland@linenergy.com; JHernandez@linenergy.com; fred@etechnv.com; Bratcher, Mike, EMNRD  
**Subject:** Turner B 113 spill: arch requirements, spill map  
**Attachments:** Turner B 113-093011 spill-spill map-100311.jpg

Gentlemen,

The spill that recently occurred just north of the Turner B 113 will require an arch survey, and pending upon the results of the arch survey, may require a monitor.


The spill map is attached.

Thank you for your attention to this concern,

### **Terry Gregston**

Environmental Protection Specialist  
Bureau of Land Management  
620 E. Greene St.  
Carlsbad, NM 88220  
Office (575) 234-5958  
Cell (575) 361-2635  
Fax (575) 234-5927

**Confidentiality Warning:** This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.



030

Linn Operating Spill: 12NU001TG (temporary tracking number)

T17s, R31e, section 30

LA 43319

Spill Oil and Saltwater 0.2.368

TURNER B #113

