

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

MAR 24 2015

Form C-141  
Revised August 8, 2011

**RECEIVED** to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1508 334759** **229137** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Bose Ikard 4 State Com #18H	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-42404
----------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	4	17S	29E	330'	South	330'	West	Eddy

Latitude 32.857365757189 Longitude -104.087356260491

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 155 bbls PW	Volume Recovered: 150 bbls PW
Source of Release: Poly Flowline	Date and Hour of Occurrence: 3/2/2015 1:30 pm	Date and Hour of Discovery: 3/2/2015 1:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Garrett Merket	Date and Hour: 3/2/2015 9:15 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by when a weld on a ploy flow failed. Vacuum trucks were dispatched to recover all standing fluid and the poly line repaired.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred in the pasture and is approximately 100' x 120' in size. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist 	
Title: Senior Environmental Coordinator	Approval Date: 3/24/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: March 23, 2015 Phone: 575-748-6940	<b>Remediation per O.C.D. Rules &amp; Guidelines</b> <b>SUBMIT REMEDIATION PROPOSAL NO</b> <b>LATER THAN: 4/24/15</b>	

\* Attach Additional Sheets If Necessary

2RP. 2913

## **Bratcher, Mike, EMNRD**

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Monday, March 23, 2015 6:06 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Subject:** (C-141 Initial) Bose Ikard 4 State Com #18H (30-015-42404)  
**Attachments:** 3-2-2015 Bose Ikard 4 State Com #18H (FL) Initial.pdf

Mike,

Attached is a C-141 Initial for your consideration. Please feel free to contact me if you have any questions or concerns.

Thank you,

### **Amanda Trujillo**

Senior Environmental Coordinator  
COG Operating LLC  
Cell: 505.350.1336  
Office: 575.748.6930  
[atrujillo@concho.com](mailto:atrujillo@concho.com)

2407 Pecos Ave.  
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

---

**From:** Garrett Merket  
**Sent:** Monday, March 02, 2015 9:15 AM  
**To:** [mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us); [heather.patterson@state.nm.us](mailto:heather.patterson@state.nm.us)  
**Subject:** (Notification) Bose Ikard 4 State Com #18H (30-015-42404)

Mr. Bratcher,

COG Operating LLC is reporting a release on the Bose Ikard 4 State Com 18H (30-015-42404).  
Unit M Section 4, Township 17S Range 29E.

The release occurred at 1:30 AM on 3/2/2015.  
Released: 0.12 Barrels Oil; 155 Barrels Produced Water  
Recovered: 0.12 Barrels Oil; 150 Barrels Produced Water

The released was caused by a bad weld on a poly flow line. The site is being evaluated for clean-up and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thanks!

**Garrett B. Merket**  
Environmental Coordinator  
COG Operating, LLC  
Cell: 432-234-0590

2208 W. Main St.  
Artesia, NM 88210

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.