

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <i>Enterprise Field Services LLC</i>	Contact: <i>Jim Heap</i>
Address: <i>PO Box 4324, Houston, TX 77252</i>	Telephone No.: <i>432-686-5404</i>
Facility Name: <i>Gathering Line #1009</i>	Facility Type: <i>Gathering Pipeline</i>

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<i>15</i>	<i>22S</i>	<i>31E</i>					<i>Eddy</i>

Latitude: *N 32.39359* Longitude: *W -103.7009*

NATURE OF RELEASE

Type of Release: <i>Natural Gas</i>	Volume of Release: <i>376 Mscf</i>	Volume Recovered: <i>0</i>
Source of Release: <i>Pipeline Leak</i>	Date and Hour of Occurrence: <i>1/31/2014 @ 17:00 MDT</i>	Date and Hour of Discovery: <i>1/31/2014 @ 17:30 MDT</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

CAUSE: Hydrate build-up required the line to be blown-down to atmosphere

ACTION: The line was blocked-in and blown down; event ended at 16:20 MDT. Volume of Release includes the blow-down volume.

Describe Area Affected and Cleanup Action Taken.*


All gas was lost to atmosphere.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Jon E. Fields</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <i>Director - Field Environmental</i>	Approval Date: <i>4/13/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>jefields@eprod.com</i>	Conditions of Approval: <input checked="" type="checkbox"/> Guidelines <input type="checkbox"/> Remediation	
Date: <i>2-5-2014</i> Phone: <i>713-381-6684</i>	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 5/13/15



2RP-2944




Enterprise
Products

ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

February 5, 2014



7013 1090 0000 1023 4610
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report
Gas Loss Reported in the Carlsbad Gathering Field**

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC please find enclosed the requisite C-141 Form for the January 31, 2014 release from our 1009 Line in our Carlsbad Gathering Field, Eddy County. The release was required to relieve a hydrate blockage in the gathering line. There were no liquids associated with this release.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-381-6684.

Regards,

Jon E. Fields
Director, Field Environmental

/sjn
attachments