Bratcher, Mike, EMNRD

From: Cliff P. Brunson <cbrunson@bbcinternational.com>

Sent: Tuesday, January 22, 2013 8:36 AM

To: Bratcher, Mike, EMNRD

Cc: C J Summers; Ken Swinney; Jennifer Gilkey; Kathy Purvis

Subject: Oxy-Pure Gold B Federal #20-Remediation Plan

Attachments: Remediation Packet- Pure Gold B-20.pdf

Mike,

This e-mail is to confirm our discussion on January 14, 2013 concerning the remediation plan for the release that occurred at the Oxy Pure Gold B Federal #20. I have attached the site drawing and the summary of the laboratory data we reviewed during our discussion for your files. As agreed, Oxy will excavate 6 inches across the entire leak area at the site. The site will then be backfilled with clean soil. The depth to groundwater is this area is approximately 150-175 feet.

If you would please reply back via e-mail with your concurrence of this remediation plan, it would be greatly appreciated.

Oxy and I thank you for your assistance in handling this matter.

Thanks, Cliff

Cliff P. Brunson, CEI, CRS
President
BBC International, Inc.
World-Wide Environmental Specialists
Mailing Address:
P. O. Box 805
Hobbs, NM 88241-0805 USA
Shipping Address:
1324 W. Marland St.
Hobbs, NM 88240 USA
Phone: (575) 397-6388
Fax: (575) 397-0397


E-Mail: cbrunson@bbcinternational.com

Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.



Оху

Pure Gold B Federal #20



U/L P, Section 20, T23S, R31E 1260' FSL and 250' FEL Eddy County, NM N 32.285970° W 103.7916°

BBC Inter	national, inc.
	Оху
Pure Gold	B Federal #20
42/44/42	DDWC L W D

Date: 12/11/12	DRWG by: K. Purvis
NOT TO SCALE	File: Oxy 2012

Laboratory Analytical Results Summary Pure Gold B Federal #20

		Sample	SP1 @ 1'	SP1@3'	SP1 @ 5'
Analyte	Method	Date	12/20/12	12/20/12	12/20/12
			mg/Kg	mg/Kg	mg/Kg
Benzene	BTEX 8021B		<0.050	N/A	N/A
Toluene	BTEX 8021B		<0.050	N/A	N/A
Ethylbenzene	BTEX 8021B		<0.050	N/A	N/A
Total Xylenes	BTEX 8021B		<0.150	N/A	N/A
Total BTEX	BTEX 8021B		<0.300	N/A	N/A
Chloride	SM4500CI-B		240	544	240
GRO	TPH 8015M		<10.0	N/A	N/A
DRO	TPH 8015M		<10.0	N/A	N/A

		Sample	SP2 @ 1'	SP2 @ 3	SP2 @ 4"
Analyte	Method	Date	12/20/12	12/20/12	12/20/12
			mg/Kg	mg/Kg	mg/Kg
Chloride	SM4500CI-B		288	384	240

		Sample	SP3 @ 1	SP3 @ 2'
Analyte	Method	Date	12/20/12	12/20/12
			mg/Kg	mg/Kg
Benzene	BTEX 8021B		<0.050	N/A
Toluene	BTEX 8021B		<0.050	N/A
Ethylbenzene	BTEX 8021B		<0.050	N/A
Total Xylenes	BTEX 8021B		<0.150	N/A
Total BTEX	BTEX 8021B		< 0.300	N/A
Chloride	SM4500CI-B		128	96
GRO	TPH 8015M		<10.0	N/A
DRO	TPH 8015M		<10.0	N/A

		Sample	SP4 @ 1	SP4 @ 2'
Analyte	Method	Date	12/20/12	12/20/12
			mg/Kg	mg/Kg «
Chloride	SM4500CI-B		32	48

		Sample	SP5 @ 1"	SP5 @ 2'
Analyte	Method	Date	12/21/12	12/21/12
			mg/Kg	mg/Kg
Benzene	BTEX 8021B		<0.050	N/A
Toluene	BTEX 8021B		<0.050	N/A
Ethylbenzene	BTEX 8021B		<0.050	N/A
Total Xylenes	BTEX 8021B		<0.150	N/A_
Total BTEX	BTEX 8021B		<0.300	N/A
Chloride	SM4500CI-B		64	80
GRO	TPH 8015M		<10.0	N/A
DRO	TPH 8015M		<10.0	N/A

		Sample	SP6 @ 1'	SP6 @ 2
Analyte	Method	Date	12/21/12	12/21/12
			mg/Kg	mg/Kg
Chloride	SM4500CI-B		64	48




Groundwater Plot

OXY Pure Gold B Federal #20

County Unit Letter Section Eddy P 20

Township 23S Range 31E

Trend Map 150'-175'



⇔ Location

OCD

♥USGS

SEO

All Databases



Section Quarters

Oxy Pure Gold B Federal #20

CountyUnit LetterSectionTownshipRangeEddyP2023S31E

Trend Map 150'

. 2

NW/NW	NENW	NW/NE	NEZNE
None			
Unit Letter D	Unit Letter C	Unit Letter B	Unit Letter A
SWINW	SE/NW	SW/NE	SENE
Unit Letter E NW/SW	Unit Letter F NE/SW	Unit Letter G NW/SE	Unit Letter H NE/SE
Unit Letter L SW/SW	Unit Letter K SE/SW	Unit Letter J SW/SE	Unit Letter I SE/SE
	1 1 1		
Unit Letter M	Unit Letter N	Unit Letter O	Unit Letter P

3

4

Location

OCD

USGS

SEO

All Databases

<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003 Submit 2 Copies to appropriate District Office in accordance

Attached [

with Rule 116 on back side of form

Form C-141

	Salita Fe, INIV 87303											
Release Notification and Corrective Action												
	OPERATOR · 🔀 Initial Report 🔲 Final Repor									Final Report		
Name of Company Oxy Permian Ltd.						Contact CJ Summers						
		tanolind Rd,		ИМ		Telephone No. (575) 397-8216						
Facility Nar	Facility Name Pure Gold B Federal #20					Facility Typ	e Gathering					
Surface Ow	ner BLI	М		Mineral C)wner			Lease 1	No. NM-38	463		
				LOCA	TIO	N OF RE	LEASE					
Unit Letter	Section	Township	Range	Feet from the		/South Line	Feet from the	East/West Line	County			
P	20	238	31E	1260		South	250	East	Eddy			
<u> </u>	 	,		Latitude N 32.1	28597°	Longit	u de W 103.7916	5°				
						OF REL						
Type of Rele						Volume of	Release 20 bb		Recovered	0 bbls		
Source of Re	lease 2" \	Y Strainer with	h ¼" hole	around		1	lour of Occurrenc @ 8:00 am	te Date and	Hour of Di	scovery		
Was Immedia	ate Notice (Yes [] No 🔲 Not Re	equired	If YES, To Mike Brate	Whom? ther- OCD; James	s Amos- BLM				
By Whom?	Chancey	Summers				Date and F	lour 12/7/2012	@ 2:10 pm	······································			
Was a Water						Date and Hour 12/7/2012 @ 2:10 pm If YES, Volume Impacting the Watercourse.						
			Yes 🗵] No		}	1.					
If a Watercou	irse was In	pacied. Descr	ibe Fully.	*				······································				
Describe Car	ise of Probl	em and Reme	dial Actio	n Taken.*			•					
A 2" Y Strair	ier with ¼"	hole around	caused 20	bbls of produced	water to	leak onto the	ground. The sou	irce of the leak was	s repaired.			
		0.00										
Describe Are	a Affected	and Cleanup.	Action Tal	ken.*			•					
The area affe	cted is app	roximately 20	0° x 20°. 1	Remediation will	be perfi	ormed in acco	rdance with an O	CD and BLM appr	oved remed	iation p	lan.	
								inderstand that pur				
regulations a	II operators	are required t	o report a	nd/or file certain r	elease i	notifications a	nd perform correc	tive actions for rel	eases which	may e	ndanger	
should their	or the envi	ronment. The nave failed to	: acceptano adequately	ce of a C-141 repo	ort by th emedia	te OMOCD in	iarked as "Final R ion that pose a thr	eport" does not rel eat to ground wate	ieve the ope	rator o gree bu	i liability man health	
or the environ	nment. In a	iddition, NM(OCD accep	ntance of a C-141	report of	loes not reliev	e the operator of	responsibility for c	compliance	with an	y other	
federal, state.	or local la	ws and/or regi	alations.		· · · · · · · · · · · · · · · · · · ·							
					1		<u>OIL CON</u>	<u>SERVATION</u>	DIVISION	<u>NC</u>		
Signature:)			•					
						Approved by	District Supervis	or:				
Printed Name	:: Chane	ey Summers										
Title: HES	Specialist					Approval Da	le:	Expiration	Date:			
E-mail Addre	ess: Char	ncey.Summers	@oxy.coi	11		Conditions o	f Approval:			ات ،		

Phone: (575) 397-8216

¹²⁻¹⁸⁻¹² * Attach Additional Sheets If Necessary