

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
AUG 23 2013
NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

| | | | |
|----------------------|---|------------------------------|----------------|
| Name of Company | COG Operating LLC | Contact | Pat Ellis |
| Address | 600 West Illinois Avenue, Midland, TX 79701 | Telephone No. | (432) 230-0077 |
| Facility Name | Dodd Federal Unit #128 | Facility Type | Well Location |
| Surface Owner: State | Mineral Owner | Lease No. (API#)30-015-25864 | |




LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| F | 10 | 26S | 28E | | | | | Eddy |

Latitude N32.84810 ° Longitude W104.03795 °

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release: Produced Water | Volume of Release 700 bbls | Volume Recovered 650 bbls |
| Source of Release: Victaulic clamp on header | Date and Hour of Occurrence 02/06/2013 | Date and Hour of Discovery 02/06/2013 11:30 a.m. |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Mike Bratcher - NMOCD | |
| By Whom? Michelle Mullins | Date and Hour 02/07/2013 8:05 pm | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. N/A | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* A Victaulic clamp failed on the inlet header inside the facility. The inlet header has been replaced with new components that are coated and lined. | | |
| Describe Area Affected and Cleanup Action Taken.* Tetra Tech personnel inspected the site and collected samples to define the spill extents. Soil that exceeded the RRAL was removed and hauled away for proper disposal. The site was then brought up to surface grade with clean backfill material. Tetra Tech prepared a closure report and submitted it to NMOCD for review. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |

| | | |
|--|--|-----------------------------------|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Ike Tavarez (agent for COG) | Approved by District Supervisor:  | |
| Title: Project Manager | Approval Date: 02/09/15 | Expiration Date: N/A |
| E-mail Address: Ike.Tavarez@tetrattech.com | Conditions of Approval:  | Attached <input type="checkbox"/> |
| Date: 2-15-13 Phone: (432) 682-4559 | | |

* Attach Additional Sheets If Necessary

28P-1563