

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 14 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1519833437		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Oxy Permian Ltd.		Contact Chancey Summers			
Address 6 Desta Drive, Midland, TX 79705		Telephone No. (432) 685-5824			
Facility Name Shugart 6 Fed Com #1 Battery		Facility Type Battery			
Surface Owner BLM		Mineral Owner		API No. 30-15-31313	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	15	24S	29E					Eddy County, NM

Latitude N 32.77870° Longitude W 103.90352°

NATURE OF RELEASE

Type of Release Oil	Volume of Release 8 bbls	Volume Recovered 0 bbls
Source of Release Corrosion caused a hole in the north oil tank	Date and Hour of Occurrence 06/08/2015	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson- NMOCD; James Amos- BLM	
By Whom? Kathy Purvis, BBC International	Date and Hour 06/10/2015 @ 9:33 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Corrosion caused a hole in the north oil tank which leaked 8 bbls of oil onto the ground. No fluids were recovered and the tank was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 125' x 75' with the leak both on and off location on the west side. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers		Signed By  Approved by Environmental Specialist:	
Title: HES Lead		Approval Date: 7/17/15	Expiration Date: N/A
E-mail Address: Chancey_Summers@oxy.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO <input type="checkbox"/>	
Date: 7-13-15 Phone: (432) 685-5824		LATER THAN: 8/20/15	

* Attach Additional Sheets If Necessary

2RP-3123

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Tuesday, July 14, 2015 2:15 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; jamos@blm.gov
Cc: C J Summers; Susan Miller; cbrunson@bbcinternational.com;
kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Shugart 6 Fed Com #1 Battery
Attachments: Initial C-141, Shugart 6 Fed Com #1 Battery.pdf

Attached is the initial C-141 for a leak that occurred at the Shugart 6 Fed Com #1 Battery on 06/08/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Wednesday, June 10, 2015 9:33 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; jamos@blm.gov
Cc: C J Summers; Susan Miller; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com; Kathy Purvis
Subject: Shugart 6 Fed Com #1 Battery

This is to inform you that Oxy Permian had a leak at the Shugart 6 Fed Com #1 Battery on June 8, 2015. Oxy spilled 8 bbls of oil due to corrosion causing a hole in the north oil tank. The preliminary report shows the leak measuring approximately 80' x 80' both on and off location. No fluids were recovered. The release is located in the NE ¼ of Section 6, T18S, R31E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: At the intersection of CR222 and CR250, go north on CR222 for 3.8 miles, turn west and go 1.4 miles, turn north and go 0.5 mile, go back east 0.2 mile to location. API# 30-015-31313, No GPS available at this time.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com