

NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico
Energy Minerals and Natural Resources

JUL 14 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <i>260137</i>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit #085 at James Ranch Unit #017 Battery (Battery at JRU #017 well, API 30-015-27784)	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Unknown	API No. 30-015-35322
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter L	Section 6	Township 23S	Range 31E	Feet from the 2180	North/South Line South	Feet from the 185	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.33553° Longitude -103.81980°

NATURE OF RELEASE

Type of Release Crude Oil and Produced Water	Volume of Release 4 bbls oil, 24 bbls PW	Volume Recovered None
Source of Release Flow Line	Date and Hour of Occurrence 7/10/2015 hour unknown	Date and Hour of Discovery 7/10/2015 at 12 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD), Jim Amos (BLM)	
By Whom? Amy Ruth	Date and Hour 7/10/2015 at 5:36 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Buried steel line weakened by corrosion. Line was clamped until joint of line replaced.

Describe Area Affected and Cleanup Action Taken.*
Leak affected 780 square feet of pasture west of the JRU 17 Battery pad. Leak area was covered with plastic to prevent downward migration until it is addressed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth	Signed By <i>[Signature]</i> Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: <u>7/17/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 7/14/2015	Phone: 432-661-0571	

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 8/26/15

* Attach Additional Sheets If Necessary

2RP-3128

Bratcher, Mike, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Tuesday, July 14, 2015 3:17 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: jamos@blm.gov
Subject: Initial C-141 - BOPCO James Ranch Unit 085 flowline at JRU 17 Battery 7-10-2015
Attachments: Initial C-141 - James Ranch Unit #085 (7-10-2015).pdf

Please find the attached initial form C-141 and call me with any questions/concerns. Thanks :)

Amy C. Ruth
BOPCO, L.P.
EH&S Remediation Specialist
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office: (575)887-7329
Fax: (575)887-7473
Cell: (432)661-0571

-----Original Message-----

From: Ruth, Amy C.
Sent: Friday, July 10, 2015 5:36 PM
To: Mike Bratcher; EMNRD Patterson Heather
Cc: jamos
Subject: BOPCO James Ranch Unit 085 flowline at JRU 17 Battery

BOPCO personnel discovered a leak in the flowline west of the JRU 17 Battery in the pasture at these coordinates: n 32.33553, w -103.81980. The line was clamped and will be repaired. No fluids were recovered and estimating 3.5 bbls oil and 24 bbls produced water. A C-141 will be submitted.

Bratcher, Mike, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Friday, July 10, 2015 5:36 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: jamos
Subject: BOPCO James Ranch Unit 085 flowline at JRU 17 Battery
Attachments: image.jpeg; ATT00001.txt

BOPCO personnel discovered a leak in the flowline west of the JRU 17 Battery in the pasture at these coordinates: n 32.33553, w -103.81980. The line was clamped and will be repaired. No fluids were recovered and estimating 3.5 bbls oil and 24 bbls produced water. A C-141 will be submitted.