NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

JUL 2 1 2015

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in **RECEIVED** cordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB15											Final Report		
						Contact Rudy Zuniga							
Address 64				IM 88220		No. 575-390-54	-35						
Facility Na	me Parkw	ay West Un	acility Typ	oe Oil									
Surface Owner State Mineral Owner						State			API No. 30-015-32363				
				LOCA	TION	OF REI	LEASE						
Unit Letter	1 1 1 1 1		North/	South Line	Feet from the		East/West Line County						
Α	28	19 S	29E	1310	N	North	660	E	East	Eddy			
Latitude: N 32'63'50.88" Longitude: W 104'07'33.49"													
				NATU	URE	OF RELI	EASE						
Type of Release Spill oil							Volume of Release 6 bbl Volume Recovered 5 bbls						
Source of Release						Date and Hour of Occurrence Date and Hour of Discover					scover	y	
Corrosion on bottom of tank						7.16.2015			7.16.2015	@2:30 PM			
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required							If YES, To Whom? Randy Dade @ OCD						
			Heather Patterson @OCD										
By Whom?						Date and Hour							
Jesse Armendariz						7.16.2015 3:00 PM 7.16.2015 8:00 AM							
Was a Water	rcourse Re		If YES, Volume Impacting the Watercourse										
☐ Yes ☒ No													
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.* On July 16, 2015, at 2:30 PM Devon Lease Operator was checking his route and found that the bottom of a tank had corrosion and was leaking oil into the containment. There was a total of 6 bbls of oil leaked, 5 bbls were recovered, and the other was in the gravel.													
Describe Are	a Affected	and Cleanu	p Action T	`aken.*									
Devon Lease Operator switched the production out of the leaking tank into another tank, he then emptied out the leaking tank into another tank. Legendary was called out to do cleanup and 5 bbls of oil were recovered. The other was in the gravel and unable to be recovered.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature: Corina Moya						OIL CONSERVATION DIVISION							
orginature. Cor or to refo year						Signed By My Drawers							
Printed Name: Corina Moya						Approved by Environmental Specialist:							
Title: Field A	dmin Sup	port	-		Approval Date: 7 23 5 Expiration Date: NIA								
E-mail Addre	ss: corina.	moya@dvn.c	om		(Conditions of	Approval:			Attached	_		
Date:	7.17.2015		Phone: 57	5.746.5559			per O.C.D. Ru				_		
Attach Addit				<u> </u>		BMIT REM ER THAN	EDIATION	OPOS	AL NO —		2 RF	2-3144	