

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

JUL 23 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

*NAB1520549326*

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Really Scary Federal #5	Facility Type: Battery

Surface Owner: Fee	Mineral Owner: Federal	API No. 30-015-40241
--------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	33	24S	28E	380'	South	990'	East	Eddy

Latitude 32.1675873 Longitude -104.0869827

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 20 bbls PW	Volume Recovered: 18 bbls PW
Source of Release: Filter Pot	Date and Hour of Occurrence: 6/30/2015 8:30 pm	Date and Hour of Discovery: 6/30/2015 8:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
This release was caused by a bad hose on a filter pot. Vacuum trucks were dispatched to recover all standing fluid and repairs were made to the facility.

Describe Area Affected and Cleanup Action Taken.\*  
This release occurred within the lined facility. Repairs were made to surface equipment, the facility cleaned and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Signed By <i>Mike Brennan</i> Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: <i>7/24/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>atrujillo@concho.com</i>	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: July 14, 2015 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

*2RP-3151*

## Bratcher, Mike, EMNRD

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Thursday, July 23, 2015 2:52 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; james\_amos@blm.gov  
**Cc:** Shelly Tucker; Glass, Dara  
**Subject:** (Notification/C-141 Initial-Final) Really Scary Federal Com #5 (30-015-40241)  
**Attachments:** 6-30-2015 Really Scary Federal #5 (TB) Initial-Final.pdf

Mr. Bratcher,

COG Operating LLC is reporting a release on the Really Scary Federal Com #5 (30-015-40241)  
Unit P Section 33 Township 24S Range 28E  
The release occurred at 8:30 pm on 6/30/2015  
Released: 20 bbls PW  
Recovered: 18 bbls PW

This release was caused by a bad hose on a filter pot. Vacuum trucks were dispatched to recover all standing fluid and repairs were made to the facility. This release remained within the lined facility and was able to be recovered and the facility was then put back into production. If you have any additional questions please feel free to contact me.

Thank you,

### **Amanda Trujillo**

Senior Environmental Coordinator  
COG Operating LLC  
Cell: 505.350.1336  
Office: 575.748.6930  
[atrujillo@concho.com](mailto:atrujillo@concho.com)

2407 Pecos Ave.  
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.