Patterson, Heather, EMNRD

From: Sent: To: Cc: Subject: Attachments:

21

Patterson, Heather, EMNRD Monday, July 27, 2015 6:59 AM Bob Asher Bratcher, Mike, EMNRD; 'Dolly, Ian' FW: Yates Humidor State Unit #3 Lightning Strike Yates Humidor State Unit 3 7-17-15.docx

Bob,

We received this report from SLO on the Humidor Unit 3 Lightning strike. It appears the berm was breached. The OCD will require the area outside the lined battery to be addressed.

Thank you,

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

From: Dolly, Ian [mailto:idolly@slo.state.nm.us]
Sent: Friday, July 17, 2015 9:03 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Strang, Dana V.
Subject: Yates Humidor State Unit #3 Lightning Strike

Mike and Heather, here's some additional information regarding the YPC Humidor which suffered a lightning strike earlier this week. I visited the site on Monday, 7/13 and discovered some PW escaped the berm and made it into the pasture. If you have any questions feel free to call. Thank you.

Ian Dolly New Mexico State Land Office Carlsbad District Resource Specialist idolly@slo.state.nm.us Office: 575-885-1323 Cell: 575-361-4045

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit <u>http://www.symanteccloud.com</u>

Bratcher, Mike, EMNRD

From:	Bob Asher <boba@yatespetroleum.com></boba@yatespetroleum.com>
Sent:	Monday, July 13, 2015 10:07 AM
То:	Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD; NMSLO
	(Carlsbad/Ion Dolly); NMSLO (Hobbs/Mathew Hagman); Naranjo, Mark M.; NMSLO
	(Santa Fe/Dana Vackar Strang)
Cc:	IncidentReportingNM; Amber Cannon; Chase Settle; Katie Parker; Tanna Adams;
	Veronica Alvarado
Subject:	Release Notification (Humidor

Yates Petroleum Corporation is reporting a release at the following location (7/11/2015, 10:00 AM).

Humidor State Unit #3 30-015-23599 Section 14, T24S-R27E 1980 FNL & 960 FWL Eddy County, New Mexico

Released: 30 B/PW; Recovered: 30 B/PW.

Cause of the release was from a lightning strike that hit the produced water tank. The release was contained within the bermed and lined battery, all released water was recovered. Vacuum truck(s) were called.

A Form C-141 with complete information will be submitted.

Thank you.

Robert Asher NM Environmental Regulatory Supervisor

Yates Petroleum Corporation 105 S. 4th Street

Artesia, NM 88210 575-748-4217 (Office) 575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.