

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

0AB1522950454

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Hackberry 6 Fed Com #4H	Facility Type	Well

Surface Owner	BLM	Mineral Owner		API No.	30-015-41248
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	6	19S	31E					Eddy County, NM

Latitude N 32.69558° Longitude W 103.91203°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	8 bbls	Volume Recovered	6 bbls
Source of Release	Over pressure on the stuffing box caused the packing to blow out of the well head	Date and Hour of Occurrence	07/19/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson-NMOCD, Shelly Tucker and James Amos-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	07/20/2015 @ 4:06 pm	NM OIL CONSERVATION	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	ARTESIA DISTRICT		

If a Watercourse was Impacted, Describe Fully.\*

AUG 14 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.\*

Over pressure on the stuffing box caused the packing to blow out on the well head and spill 8 bbls of oil onto the ground. A vacuum truck recovered 6 bbls of oil and the packing was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 105' x 40' on location. Remediation will be completed according to a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: CJ Summers

Title: HES Lead

E-mail Address: chancey\_summers@oxy.com

Date: 8-13-15 Phone: (432) 685-5824

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Approval Date: 8/17/15

Expiration Date: N/A

Conditions of Approval:

Attached ☐

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 9/18/15

\* Attach Additional Sheets If Necessary

2RP-3204

## **Patterson, Heather, EMNRD**

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Friday, August 14, 2015 4:23 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial C-141, Coyote 21 #2  
**Attachments:** Initial C-141, Coyote 21 #2.pdf

Attached is the initial C-141 for a leak that occurred at the Coyote 21 #2 on 07/23/15 in Eddy County, NM. Receipt notification via email is greatly appreciated.

*Kathy Purvis*

BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

## Bratcher, Mike, EMNRD

---

**From:** Jennifer Gilkey <jgilkey@bbcinternational.com>  
**Sent:** Friday, July 24, 2015 5:07 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; CJ Summers  
**Cc:** Cliff Brunson ; Ken Swinney; Kathy Purvis  
**Subject:** Coyote 21 #2

This is to inform you that Oxy Permian had a leak at the Coyote 21 #2 on July 23, 2015. Oxy spilled 5 bbls of oil and 30 bbls of produced water due to back pressure causing the stuffing box packing to leak on the well head. The preliminary report shows the leak measuring approximately 20' x 10' on location. A vacuum truck recovered 30 bbls of fluids. The release is located in the U/L N of Section 21, T24S, R29E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: From Loving, take US 285 to Malaga, turn east on Duarte Rd and go 2.5-3 miles, turn right on McDonald Rd, cross the Pecos River, turn left at the first white cattleguard and go 0.25 mile to battery and well location. API# 30-15-29864, GPS coordinates: N 32.19824° W 103.99020°

\*\*\*\*\*  
*Jennifer Gilkey*  
*Administrative Manager*  
BBC International, Inc.  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
E-mail: [jgilkey@bbcinternational.com](mailto:jgilkey@bbcinternational.com)  
1324 W. Marland Blvd.  
Hobbs, NM 88240  
\*\*\*\*\*